



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS RC AUTO		Ref:	CS/TP24090243/Kqp3m4	
160 SIN MING DRIVE		Date:	19/09/2024	
#06-20 SIN MING AUTOCITY		Code:	TP393	
SINGAPORE 575722				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	-	Veh. Inspected	SNP 5025X	
Policy No.	-	Coverage	0	
Claim No.	-	Excess	\$0.00	
Assign From	-	Assign Date	12/09/2024	
2. Vehicle Details				
Make & Model	TOYOTA VOXY (A)		C.C	1797
Engine No.	HIDDEN		Year of Reg.	
Chassis No.	ZWR900116575		Colour	METALLIC PEARL WHITE
Odometer	77430 KM		Steering	IN ORDER
Brakes	IN ORDER		General	GOOD
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
		Size	Make	Balance (mm)
R/H Front Tyre		225/50R18	YOKOHAMA	9
L/H Front Tyre		225/50R18	YOKOHAMA	9
R/H Rear Tyre		225/50R18	YOKOHAMA	9
L/H Rear Tyre		225/50R18	YOKOHAMA	9
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S SLIDING DOOR AUTO DOOR GEAR.				
5. General Information				
Accident Date			Inspection Date	12/09/2024
Survey held at	RC AUTO - 160 SIN MING DRIVE #06-20 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				
C) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,100-\$1,300				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days				

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.