

REF:

ASSIGNMENT

From: _____ Date: _____
 Estn: _____
 OD / ~~TP~~ / TP RES / OD RES / EVA / INV / MV
 To in _____ Vehicle No: _____
 at W _____ m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SMV8875d Yr Regn: 2016, Dec.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Qashqai C.O. 1197

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 160888 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R17

R: 215/60R17

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MMC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. _____

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.I. 16/09/24

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7P 111

COE Expiry: _____

Estimate given during: Yes ☒ / No ☐
 1st Survey

MV:

PV:

Nett:

607D

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Inve (\$)

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

Photos

Others

Report Format:

Report Format:

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

EE CHUAN SENG
 24 UPPER SERANGOON VIEW #15-25
 SINGAPORE 534205

Contact : 97880941 96691902

TAX INVOICE

Repair Code : CLM18377
 Date in : 14/09/2024
 Vehicle Num. : SMV8875U
 Model : NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
 Chassis/Eng# : SJNFEAJ11U1797962/HRA2340868A

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Dented</i>	1	860.40	860.40 ✓
REAR BUMPER REFLECTOR L/R <i>cut & new</i>	2	66.90	133.80 ✓
REAR BUMPER REINFORCEMENT <i>Dented</i>	1	746.20	746.20 ✓
REAR BUMPER REINFORCEMENT BRACKET L/R <i>Dented</i>	2	152.40	304.80 ✓
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	42.80	85.60 +
REAR BUMPER SPONGE <i>cut & new</i>	1	152.90	152.90 ✓
REAR BUMPER TOW HOOK COVER <i>new</i>	1	30.00	30.00 +
REAR END PANEL <i>Dented</i>	1	573.40	573.40 ✓
REAR END PANEL INNER TOP GARNISH <i>Dented</i>	1	74.90	74.90 ✓
REAR EXHAUST SILENCER BOX <i>Dented Peris (Dented)</i>	1	1352.60	1352.60 150 ✓
REAR TAILGATE <i>Dented</i>	1	3306.00	3,306.00 ✓
REAR TAILGATE 'LOGO' EMBLEM <i>new</i>	1	70.00	70.00 +
REAR TAILGATE 'QASHQAI' EMBLEM <i>new</i>	1	101.90	101.90 ✓
REAR TAILGATE DAMPER L/R <i>new</i>	2	297.00	594.00 +
REAR TAILGATE HINGES L/R <i>new</i>	2	30.00	60.00 +
REAR TAILGATE INNER PULL HANDLE <i>new</i>	1	25.00	25.00 +
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R <i>new</i>	2	15.00	30.00 +
REAR TAILGATE INNER TRIM BOARD	1	125.00	125.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

EE CHUAN SENG
 24 UPPER SERANGOON VIEW #15-25
 SINGAPORE 534205

Contact : 97880941 96691902

TAX INVOICE

Repair Code : CLM18377

Date in : 14/09/2024

Vehicle Num. : SMV8875U

Model : NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR

Chassis/Eng# : SJNFEAJ11U1797962/HRA2340868A

REAR TAILGATE LOCK STRIKER <i>new</i>	1	37.50	37.50 +
REAR TAILGATE MECHANISM LOCK <i>new</i>	1	205.50	205.50 ✓
REAR TAILGATE WEATHER STRIP <i>new</i>	1	198.40	198.40 ✓
REAR TAILGATE WINDSCREEN WITH MOULDING <i>new</i>	1	1068.00	1,068.00 168.
Subtotal before discount			10,135.90
Percentage discount 10%			1,013.59
Sub-total 1			9,122.31
REAR BUMPER CLIPS - SET <i>new</i>	1	80.00	80.00 30
REAR BUMPER REVERSE SENSOR (4 EYE) - SET <i>new</i>	1	380.00	380.00 280
REAR BUMPER TOP CHROME MOULDING <i>Best</i>	1	180.00	180.00 150
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>new</i>	1	30.00	30.00 20
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	50.00 30
REAR TAILGATE NUMBER PLATE <i>new</i>	1	25.00	25.00 +
REAR TAILGATE NUMBER PLATE HOLDER <i>new</i>	1	50.00	50.00 ✓
REAR TAILGATE OUTER GARNISH CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1	80.00	80.00 60

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

EE CHUAN SENG
24 UPPER SERANGOON VIEW #15-25
SINGAPORE 534205

Contact : 97880941 96691902

TAX INVOICE

Repair Code : CLM18377
Date in : 14/09/2024
Vehicle Num. : SMV8875U
Model : NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Chassis/Eng# : SJNFEAJ11U1797962/HRA2340868A

Subtotal before discount	905.00
Percentage discount 0%	0.00
Sub-total 2	905.00
Parts-total	10,027.31

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	80.00 ✓
To remove, reinstall tailgate windscreen	150.00 120
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	80.00 60
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,000.00 600
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	100.00 80
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,000.00 600
To apply anti-rust chemical on repaired and replaced panel.	100.00 60
To remove, reinstall tailgate mechanism and check for function	80.00 60
Labour Total	2,590.00
Parts & Labour Total	12,617.31

LKK Auto Consultants hence notify the Repairer of the following:

- This is a computer-generated document which requires no signature.***
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lij
2/5 17/09/24
06 Days