

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Toh, Yuslinda

Date: 18 Sep 2024

**Preliminary Advice**

Vehicle No	: SLZ727H	Accident Date	: 12/09/2024
Make	: AUDI Q4	Policy No.	: 7240171637
Assignment Date	: 16/09/2024	Excess	: S\$600.00
Date of Inspection	: 17/09/2024	Est. Duration of Repair	: 4
Inspection At	: 24 BENOI SECTOR, SINGAPORE 629857 REPAIRER: PREMIUM AUTOMOBILES PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	37,112.00
Revised Amount	:S\$	19,201.00
Check Items (Estimated)	:S\$	7,081.00
Total	:S\$	25,282.00

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	250,000.00
COE / PARF Rebate	:S\$	136,563.00
Salvage Value	:S\$	
Margin for Repair	:S\$	113,437.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.