

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0685/2024/KS
DATE : 13-Sep-24
WIP : 30891

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 17/9/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Hi Taufikh,

13 Days - OK - Allan Boo

6-Nov-24

OWNER'S NAME : MISS MATHILDA DE BOER-LIM WEN-SZE
ADDRESS : 521 YIO CHU KANG ROAD
#02-86
SINGAPORE 787086
TELEPHONE : HP +65 81687751
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : -
VEHICLE NO : **SLZ 727 H**
MODEL CODE : AUDI Q4 SPORTBACK 45 E-TRON
MODEL YEAR : 29/8/2024
ENGINE NO : EDFA
CHASSIS NO : WAUZZZFZ9RP074249
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Sep-24
PLACE OF ACCIDENT : 301 ALEXANDRA ROAD, SINGAPORE 159968

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLZ 727 H

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS	
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS AND OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE.	S/N \$	800.00	\$	500.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	\$	500.00
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER SPOILER, FRONT BUMPER TRIM, BONNET AND BOTH FRONT WHEEL ARCH TRIMS.	\$	4,500.00	\$	1,800.00
5	TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR AND DISTANCE REGULATION.	S/N \$	800.00		
6	TO CARRY OUT DE-ENERGEISING HIGH VOLTAGE SYSTEM, DEACTIVATION AND ACTIVATION.	S/N \$	480.00	\$	480.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	\$	292.00
	ADD LABOUR - SUPPLEMENTARY			\$	5,500.00
	TOTAL LABOUR CHARGES	:	\$ 9,752.00	\$	9,552.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLZ 727 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,411.00	\$ 1,128.80
2	FRONT BUMPER FIXING PARTS	1	\$ 517.00	
3	FRONT BUMPER COVER CAP - LH / RH	2	\$ 50.00	
4	FRONT BUMPER TRIM	1	\$ 496.00	\$ 396.80
5	FRONT BUMPER CLOSING ELEMENT	1	\$ 277.00	\$ 221.60
6	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 236.00	
7	FRONT BUMPER GRILLE - CENTER1	1	\$ 247.00	\$ 197.60
8	FRONT BUMPER SPOILER	1	\$ 818.00	\$ 654.00
9	FRONT BUMPER IMPACT PROTECTION - SELENITE SIL	1	\$ 545.00	\$ 436.00
10	FRONT BUMPER AIR DUCT	1	\$ 109.00	\$ 86.80
11	RADIATOR GRILLE	1	\$ 1,712.00	\$ 1,369.60
12	AUDI EMBLEM	1	\$ 202.00	\$ 161.60
13	VEHICLE ENVIRONMENT CAMERA	1	\$ 1,298.00	
14	VEHICLE ENVIRONMENT CAMERA BRACKET	1	\$ 53.00	
15	VEHICLE ENVIRONMENT CAMERA BRACKET SECURING	1	\$ 42.00	
16	FRONT PARKING AID SENSOR	2	\$ 600.00	
17	FRONT PARKING AID SENSOR SEAL RING	4	\$ 57.00	
18	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 122.00	
19	FRONT REINFORCEMENT BEAM	1	\$ 1,307.00	\$ 1,045.60
20	FRONT BUMPER SUPPORT	1	\$ 57.00	
SUB TOTAL SPARE PARTS		:	\$ 10,156.00	\$ 5,698.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLZ 727 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 5,698.40
21	FRONT FOAM FILLER PIECE	1 \$	137.00	\$ 109.60
22	LED HEADLIGHT - LH / RH	2 \$	9,788.00	\$ 7,830.40
23	LED HEADLIGHT MOUNTING - LH / RH	2 \$	300.00	\$ 240.00
24	LIFT CYLINDER - LH / RH	2 \$	504.00	
25	LIFT CYLINDER HOSE - LH / RH	1 \$	128.00	
26	BONNET	1 \$	3,668.00	
27	BONNET ATTACHMENT PARTS	1 \$	133.00	
28	BONNET HINGE - LH / RH	2 \$	178.00	
29	BONNET STRIKER - LH / RH	2 \$	260.00	
30	BONNET IMPACT PROTECTION	1 \$	36.00	
31	BONNET LOCK - LH / RH	2 \$	982.00	
32	BONNET BOWDEN CABLE - CENTER	1 \$	71.00	
33	BONNET BOWDEN CABLE COVER	1 \$	12.00	
34	BONNET RELEASE ELEMENT	1 \$	73.00	
35	FRONT WHEEL ARCH COVER - LH / RH	2 \$	274.00	\$ 216.80
36	FRONT NO PLATE	S/N \$	60.00	\$ 60.00
	ADD PARTS - SUPPLEMENTARY			\$ 4,393.44
37	SUNDRIES	\$	600.00	
TOTAL SPARE PARTS			\$ 27,360.00	\$ 18,548.64
TOTAL LABOUR CHARGES			\$ 9,752.00	\$ 9,552.00
GRAND TOTAL			\$ 37,112.00	\$ 28,100.64

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0685/2024/KS 19-Sep-24 GEORGE WONG 1 of 1 SLZ 727 H AUDI Q4 SPORTBACK 45 E-TRON	
Quantity	Description		Unit Price	Amount
Labours				
1	TO REMOVE AND TRANSFER RHS FRONT DOOR MULTI - LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N	\$ 250.00	\$ 250.00
2	TO DISMANTLE RENEW FRONT RHS DOOR.		\$ 500.00	\$ 500.00
3	TO RESPRAY RHS FRONT DOOR AND DOOR COVER.		\$ 750.00	\$ 750.00
4	TO REMOVE AND REINSTALL AIRCON CONDENSER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N	\$ 1,800.00	\$ 1,800.00
5	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N	\$ 1,200.00	\$ 1,200.00
6	TO REMOVE AND RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.		\$ 1,000.00	\$ 1,000.00
Parts				
1	FRONT DOOR - RH	1	\$ 3,340.00	\$ 2,672.00 bt✓
2	FRONT DOOR OUTER SEAL - RH	1	\$ 275.00	\$ 220.00 nec ✓
3	FRONT DOOR COVER - RH	1	\$ 445.00	\$ 356.00 de ✓
4	FRONT LOCK CARRIER	1	\$ 821.00	\$ 656.40 cra ✓
5	FRONT BUMPER REINFORCEMENT BEAM BOTH SUPPORT		\$ 125.00	\$ 100.00 de ✓
6	RADIATOR AIR GUIDE CENTER		\$ 155.00	\$ 123.60 de ✓
7	READY MIX-COOLANT 1LITER	6	\$ 332.00	\$ 265.44 nec ✓
	PART		\$ 5,493.00	\$ 4,393.44
	LABOUR		\$ 5,500.00	\$ 5,500.00
	GRAND TOTAL		\$ 10,993.00	\$ 9,893.44

For Premium Automobiles Pte Ltd

Authorised Signature



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT