



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0685/2024/KS 19-Sep-24 GEORGE WONG 1 of 1 SLZ 727 H AUDI Q4 SPORTBACK 45 E-TRON
Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND TRANSFER RHS FRONT DOOR MULTI - LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES. S/N	\$ 250.00	✓
2	TO DISMANTLE RENEW FRONT RHS DOOR.	\$ 500.00	✓
3	TO RESPRAY RHS FRONT DOOR AND DOOR COVER.	\$ 750.00	✓
4	TO REMOVE AND REINSTALL AIRCON CONDENSER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. S/N	\$ 1,800.00	✓
5	TO CARRY OUT VACUUM AND REGAS FOR R1234. S/N	\$ 1,200.00	✓
6	TO REMOVE AND RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.	\$ 1,000.00	✓
Parts			
1	FRONT DOOR - RH 1	\$ 3,340.00	dd- 2672
2	FRONT DOOR OUTER SEAL - RH 1	\$ 275.00	nec- 220
3	FRONT DOOR COVER - RH 1	\$ 445.00	nec- photo 356
4	FRONT LOCK CARRIER 1	\$ 821.00	con- 656.40
5	FRONT BUMPER REINFORCEMENT BEAM BOTH SUPPORT	\$ 125.00	bt- 100
6	RADIATOR AIR GUIDE CENTER	\$ 155.00	de- 123.60
7	READY MIX-COOLANT 1LITER 6	\$ 332.00	nec- 265.44
GRAND TOTAL		\$ 10,993.00	

For Premium Automobiles Pte Ltd

+ 4 days

Authorised Signature

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408066
 TEL : 6386 2323 FAX : 6341 1183
 EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLZ 727 H

AG - faulted
- 4 days

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,411.00	de
2	FRONT BUMPER FIXING PARTS	1	\$ 517.00	X
3	FRONT BUMPER COVER CAP - LH / RH	2	\$ 50.00	?
4	FRONT BUMPER TRIM	1	\$ 498.00	de
5	FRONT BUMPER CLOSING ELEMENT	1	\$ 277.00	crs
6	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 238.00	?
7	FRONT BUMPER GRILLE - CENTER 1	1	\$ 247.00	de
8	FRONT BUMPER SPOILER	1	\$ 818.00	3 de
9	FRONT BUMPER IMPACT PROTECTION - SELENITE SIL	1	\$ 545.00	dis
10	FRONT BUMPER AIR DUCT	1	\$ 109.00	2 de
11	RADIATOR GRILLE	1	\$ 1,712.00	ang
12	AUDI EMBLEM	1	\$ 202.00	ant
13	VEHICLE ENVIRONMENT CAMERA	1	\$ 1,298.00	?
14	VEHICLE ENVIRONMENT CAMERA BRACKET	1	\$ 53.00	?
15	VEHICLE ENVIRONMENT CAMERA BRACKET SECURING	1	\$ 42.00	?
16	FRONT PARKING AID SENSOR	2	\$ 600.00	?
17	FRONT PARKING AID SENSOR SEAL RING	4	\$ 57.00	?
18	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 122.00	?
19	FRONT REINFORCEMENT BEAM	1	\$ 1,307.00	7bt
20	FRONT BUMPER SUPPORT	1	\$ 57.00	?
SUB TOTAL SPARE PARTS		:	\$ 10,156.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLZ 727 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	FRONT FOAM FILLER PIECE	1	\$	137.00	de
22	LED HEADLIGHT - LH / RH	2	\$	9,788.00	car
23	LED HEADLIGHT MOUNTING - LH / RH	2	\$	300.00	car
24	LIFT CYLINDER - LH / RH	2	\$	504.00	?
25	LIFT CYLINDER HOSE - LH / RH	1	\$	128.00	?
26	BONNET	1	\$	3,668.00	X
27	BONNET ATTACHMENT PARTS	1	\$	133.00	X
28	BONNET HINGE - LH / RH	2	\$	178.00	X
29	BONNET STRIKER - LH / RH	2	\$	260.00	X
30	BONNET IMPACT PROTECTION	1	\$	36.00	X
31	BONNET LOCK - LH / RH	2	\$	982.00	X
32	BONNET BOWDEN CABLE - CENTER	1	\$	71.00	X
33	BONNET BOWDEN CABLE COVER	1	\$	12.00	X
34	BONNET RELEASE ELEMENT	1	\$	73.00	X
35	FRONT WHEEL ARCH COVER - LH / RH	2	\$	274.00	re - photo
36	FRONT NO PLATE	S/N	\$	80.00	ht -
37	SUNDRIES		\$	600.00	?
TOTAL SPARE PARTS		:	\$	27,360.00	
TOTAL LABOUR CHARGES		:	\$	9,752.00	
GRAND TOTAL		:	\$	37,112.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.