

Date: 14/09/2024

Vehicle No: SNS4124J

Model: TESLA MODEL Y RWD

Chassis: LRWYHCF5XRC631045-2024

Reg.Year: 2024

Third Party Insurer: INDIA INSURANCE

Third Party Veh No: GBM4591S

Date of Accident: 13/09/2024

Estimator: TING AN

Surveyor:

NOT AUTHORISED
Running B&Pain

4 days

83022.15

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR FENDER LH	1		By \$1,551.40 ✓
2	REAR FENDER QUARTER GLASS LH	1		Na \$121.50 ✓
3	REAR FENDER WHEEL ARCH LH	1		Na \$65.42 ✓
4	REAR DOOR LH	1		REPAIR
5	REAR RIM LH	1		REPAIR
SUB TOTAL				\$1,738.32
COST +10%				\$173.83
PARTS TOTAL				\$1,912.15 ✓

Finalize- Parts: \$1912.15

Nett: \$70

Labour: \$1050

p.p. 2 83022.15

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR FENDER QUARTER GLASS SEALANT	1		Na \$100.00 50 4050 ✓
2	REAR FENDER WHEEL ARCH CLIPS LH	1		Na \$50.00 20 ✓
S/N TOTAL				\$150.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$1,000.00 600

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR FENDER LH, REAR DOOR LH, REAR RIM LH & ETC.

\$1,000.00 2500

LABOUR CHARGES TO REMOVE & REPLACE REAR FENDER QUARTER GLASS LH & ETC.

\$150.00 600

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM LH, UPHOLDSTERY CUSHION SET & ETC.

\$500.00 1200

TO DAIGNOSIS FAULT CODE & ETC.

Na \$250.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$150.00 200

LABOUR TOTAL \$3,050.00

TING AN

TOTAL

\$5,112.15

Head office

8 Kung Chang Road Singapore 159143

Tel: (+65) 6472 1312 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave. 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1003

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

