

Date: 14/09/2024
Vehicle No: SNS4124J
Model: TESLA MODEL Y RWD
Chassis: LRWYHCFXRC631045-2024
Reg.Year: 2024

*Not authorized
Runny B & pain
4 days*

Third Party Insurer: INDIA INSURANCE
Third Party Veh No: GBM4591S
Date of Accident: 13/09/2024
Estimator: TING AN
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR FENDER LH	1		<i>By</i> \$1,551.40 ✓
2	REAR FENDER QUARTER GLASS LH	1		<i>By</i> \$121.50 ✓
3	REAR FENDER WHEEL ARCH LH	1		<i>By</i> \$65.42 ✓
4	REAR DOOR LH	1		REPAIR
5	REAR RIM LH	1		REPAIR
SUB TOTAL				\$1,738.32
COST +10%				\$173.83
PARTS TOTAL				\$1,912.15

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR FENDER QUARTER GLASS SEALANT	1		\$100.00
2	REAR FENDER WHEEL ARCH CLIPS LH	1		\$50.00
S/N TOTAL				\$150.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

600
\$1,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR FENDER LH, REAR DOOR LH, REAR RIM LH & ETC.

2500
\$1,000.00

LABOUR CHARGES TO REMOVE & REPLACE REAR FENDER QUARTER GLASS LH & ETC.

600
\$150.00

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM LH, UPHOLDSTERY CUSHION SET & ETC.

\$500.00 *1200*

TO DAIGNOSIS FAULT CODE & ETC.

\$250.00 *7*

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$150.00 *200*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

LABOUR TOTAL \$3,050.00

TING AN

TOTAL \$5,112.15