

Wheelz 4 You

not Aullout
nu
no any
18/9/24
2/55 6700/
7 days
telephone. After rep -
Date: 18/09/2024

To: Motor Claims Department

Vehicle No: GBG7111G

Model: NISSAN CABSTAR

ESTIMATE For GBG7111G NISSAN CABSTAR

Nett item

QTY	Parts	Amount
1	LH WING MIRROR <i>but/nu ✓</i>	\$ 303.00 ✓
1	LH WING MIRROR COVER <i>11X</i>	\$ 197.00 X
1	FRONT WIPER PANEL <i>2X</i>	\$ 794.00 X
1	FRONT PANEL <i>2X</i>	\$ 2,008.00 X
1	FRONT PANEL EMBLEM (CABSTAR) <i>nu ✓</i>	\$ 66.00 ✓
2	HEADLAMP @\$727/PC <i>nu/cno o/s Mth cno</i>	\$ 1,454.00 ✓
1	RADIATOR GRILLE <i>cno ✓</i>	\$ 799.00 ✓
1	RADIATOR GRILLE LOGO <i>nu ✓</i>	\$ 95.00 ✓
1	AIR CON BLOWER UNIT <i>11X</i>	\$ 1,218.00 X
1	AIR CON EVAPORATOR UNIT <i>11X</i>	\$ 1,588.00 X
1	FRONT BUMPER <i>but ✓</i>	\$ 1,254.00 ✓
1	FRONT BUMPER BRACKET <i>c/w hys X</i>	\$ 368.00 X
1	FRONT BUMPER REINFORCEMENT <i>nu X</i>	\$ 756.00 X
1	LH FRONT CORNER PANEL <i>22 ✓</i>	\$ 567.00 ✓
1	LH FRONT STEP PANEL GARNISH <i>11X</i>	\$ 283.00 X
1	LH FRONT DOOR <i>2X</i>	\$ 2,296.00 X
1	LH FRONT DOOR TAPE <i>11X</i>	\$ 128.00 X
1	LH FRONT DOOR HINGE(TOP) <i>11X</i>	\$ 168.00 X
1	LH FRONT DOOR HINGE(BTM) <i>11X</i>	\$ 168.00 X
1	LH FRONT DOOR CHECKER <i>11X</i>	\$ 162.00 X
1	TAILGATE <i>22/34 ✓</i>	\$ 2,099.00 ✓
4	TAILGATE HINGE @\$145/PC <i>2X</i>	\$ 580.00 X
1	TAILGATE STICKER(NISSAN) <i>nu ✓</i>	\$ 186.00 ✓
2	TAILGATE L BRACKET @\$289/PC <i>R X</i>	\$ 578.00 X
2	TAILGATE L BRACKET PIN @\$88/PC <i>nu X</i>	\$ 176.00 X
1	REAR FLOOR PANEL <i>2X</i>	\$ 3,587.00 X
2	TAILLAMP @\$268/PC <i>cno ✓</i>	\$ 536.00 ✓
2	TAILLAMP BRACKET @\$156/PC <i>nu X</i>	\$ 312.00 X
1	REAR END PANEL <i>but ✓</i>	\$ 786.00 ✓
2	REAR NUMBER PLATE LAMP @\$186/PC <i>11X</i>	\$ 372.00 X
1	SPARE TYRE CARRIER <i>11X</i>	\$ 318.00 X
1	SPARE TYRE FASTENER <i>11X</i>	\$ 165.00 X
2	REAR CORNER BRACKET @\$175/PC <i>nu/c but 1pc</i>	\$ 350.00 1pc
2	REAR CONER BRACKET RUBBER @\$40/PC <i>M5701 1pc</i>	\$ 80.00 1pc
2	REAR MUD GUARD PANEL @\$449/PC <i>22 nu/c X</i>	\$ 898.00 X
1	FRONT WINDSCREEN MOULDING <i>11X</i>	\$ 189.00 X
Parts Sum:		\$ 25,884.00
Parts Less 10% :		\$ 2,588.40
Parts Total:		\$ 23,295.60

Special Nett Items

1	LH FRONT DOOR COMPANY STICKER <i>nu 30 S/W</i>	\$ 40.00 30 S/W
1	70KM/HR STICKER <i>nu 10</i>	\$ 40.00 10 S/W
1	13 PAX STICKER <i>nu 10</i>	\$ 40.00 10 S/W
1	REVERSE SENSOR <i>Baye 200</i>	\$ 250.00 200 S/W

1	TAILGATE RIVET	11 X	\$	80.00 X
1	FRONT PANEL BODY SEALANT	11 X	\$	80.00 X
1	REAR FLOOR PANEL BODY SEALANT	11 X	\$	80.00 X
1	FRONT NUMBER PLATE	Ref 35	\$	45.00 35 s/n
1	REAR NUMBER PLATE	Ref 35	\$	45.00 35 s/n
1	FRONT WINDSCREEN INNER SEAL	11 X	\$	80.00 X
1	FRONT WINDSCREEN SEALANT	11 X	\$	40.00 X
Special Nett Items Total:			\$	820.00

Labour & Misc Charges

Description	Amount
TO FOCUS HEADLAMP	\$ 50.00 30
TO REMOVE/REFIX FRONT WINDSCREEN	\$ 11 150.00 X
TO REMOVE/REFIX DASHBOARD TO FACILITATE REPAIR	\$ 11 350.00 X
TO VACUUM AND TOP UP AIR CON GAS	\$ 11 120.00 X
TO REMOVE/REFIX AIR CON EVAPORATOR UNIT AND BLOWER UNIT	\$ 11 350.00 X
TO RUSTPROOF ON ACCIDENT DAMAGE AREA	\$ 250.00 50
TO APPLY BODY SEALANT ON CAR JOINTS	\$ 11 250.00 X
TO INSTALL REVERSE SENSOR	\$ 50.00 30
TO PANEL BEAT, CUT OUT/REWELD PANEL	\$ 2,000.00 1000
TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA	\$ 2,000.00 1200
Labour Charges Total:	\$ 5,570.00

Parts Total:	\$ 23,235.60
Special Nett Items Total:	\$ 820.00
Labour Charges Total:	\$ 5,570.00
Total Cost Of Repair:	\$ 29,625.60
(Non-Inclusive of GST)	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-6428-40
102
5785.56
320
2310
8415.56
252
6732.48