



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)	Ref:	CS/SPF24090252/Kvp3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE)	Date:	30/10/2024
POLICE LOGISTICS BASE (PLB)	Code:	SPF
1 HEMMANT ROAD SINGAPORE 438675		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 1748S	Veh. Inspected	SNS 4009J
Policy No.	-	Coverage	0
Claim No.	ACS/105/009/2024/047 (CF)	Excess	\$0.00
Assign From	LAI PENG CHONG	Assign Date	13/09/2024

2. Vehicle Details

Make & Model	TOYOTA SIENTA (A)	C.C	1490
Engine No.	M15AY934059	Year of Reg.	06/08/2024
Chassis No.	MXPL101120908	Colour	METALLIC WHITE
Odometer	2862 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/65R15	BRIDGESTONE	9
L/H Front Tyre	185/65R15	BRIDGESTONE	9
R/H Rear Tyre	185/65R15	BRIDGESTONE	9
L/H Rear Tyre	185/65R15	BRIDGESTONE	9

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/09/2024	Inspection Date	18/09/2024
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days