

Not Withheld
 11 Day & 4400h
 Resurvey After Paint
 5 days

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number : VLB 3338

Acc: 10.9.24

S/N Parts Description

- 1 Front door LH
- 2 Front door LH lock
- 3 Front door regulator and motor LH
- 4 Front door rubber LH
- 5 Front door protector LH
- 6 Front door protector mldg LH
- 7 Front door emblem LH
- 8 Rear door LH
- 9 Rear door lock LH
- 10 Rear door regulator and motor LH
- 11 Rear door rubber LH
- 12 Rear door protector LH
- 13 Rear door protector mldg LH
- 14 Rear fender protector LH
- 15 Rear bumper
- 16 Rear wheel rim LH

Unit Price Amt

Pr	\$1,090	✓
R	\$380.00	X
n	\$580.00	X
su	\$255.00	X
nd/gw	\$392.00	—
nu	\$148.00	—
nu	\$72.00	—
Rn	\$1,052.00	✓
R	\$368.00	X
n	\$542.00	X
su	\$235.00	✓
nd/gw	\$365.00	—
nu	\$138.00	—
gw	\$218.00	—
sun	\$1,011.00	X
nd/gw	\$905.00	✓

108

Labour

- 1 To remove and refit damaged parts \$1,000.00 550
- 2 To spray paint on affected parts \$1,200.00 800
- 3 To transfer both LH doors mechanism \$200.00 120
- 4 Wheel alignment \$120.00 60
- 5 Tuff coat on affected parts \$150.00 60

Page 1

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: