

REF: CS/AIG24090257/Anp3 (SMA 7308H)

ASSIGNMENT

From: _____ Date: _____
 Estn: _____
 OD / TP RES / CD RES / EVA / INV / MV
 To in _____ Vehicle NO: _____
 at _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)

Veh No: SMA7308H Yr Regn: 2023, Nov
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Audi A3 C.C. 999
 Colour: Grey. A/C: Insured / Std / NI / NA
 Sp. Reading: 16762 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WAUZZZGY3NA101111
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 225/45R17
 R: 225/45R17

Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front R/Bal. ob mm Rear R/Bal. ob mm
 L/Bal. ob mm L/Bal. ob mm
 D.O.A. _____ D.O.I. 16/09/24
 Survey held at Prenton
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rear a/s
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>DD ALB</u>
	<u>MV: 170K</u>
	<u>PV: 90K</u>
	<u>Nett: 80K</u>

COE Expiry: _____
 Estimate given during: Yes ()
 1st Survey: No ()
We will be advising our principal a cost of repair of \$3,484.08 before excess \$0 & GST with 3 days of repair, subject to their approval.
 (red, \$3364.92, 49%)
 334F

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) _____
 Report Format: _____

Days Of Repair: 3
 Resurvey No. of Trip: _____
 Add Fee: : Site Insp (\$) _____
 : Interview (\$) _____
 : Tech. Inve (\$) _____
 Survey Fee: _____
 Transportation: _____
 S + R.S. \$ _____
 Photos _____
 Others _____



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0680/2024/KS
DATE : 16-Sep-24
WIP : 30928

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 17/9/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept

OWNER'S NAME : MR. ONG YONG WEN (WONG YONGWEN)
ADDRESS : BLK 36 YUNNAN WALK 2
SINGAPORE 638167
TELEPHONE : HP +65 98475672
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7230114772
VEHICLE NO : **SMA 7308 H**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI
MODEL YEAR : 29/11/2023
ENGINE NO : DLA E21699
CHASSIS NO : WAUZZZGY3NA101111
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Sep-24
PLACE OF ACCIDENT : NEAR 923 JURONG WEST STREET 92, BLK 923
SINGAPORE 640923



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 7308 H.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,400.00	500
3	TO RESPRAY REAR BUMPER.	\$	1,100.00	550
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	✓
TOTAL LABOUR CHARGES		:	\$ 3,152.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 7308 H.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>behind</i>	1	\$ 1,894.00	✓ 1515.20
2	REAR BUMPER LOCKING MECHANISM - LH / RH <i>new</i>	2	\$ 36.00	+
3	REAR BUMPER TRIM - LH <i>lit</i>	1	\$ 81.00	✓ 64.08
4	REAR PARKING AID SENSOR SUPPORT - LH OUTER <i>pp</i>	1	\$ 32.00	+
5	REAR BUMPER AIR GUIDE GRILLE SENSOR - LH <i>pp</i>	1	\$ 300.00	+
6	REAR BUMPER SPOILER <i>lit</i>	1	\$ 254.00	✓ 202.80
7	REAR LIGHT REFLECTOR - LH <i>new</i>	1	\$ 41.00	+
8	REAR BUMPER REINFORCEMENT BEAM <i>new</i>	1	\$ 689.00	+,
9	REAR BUMPER GUIDE SECTION - LH <i>new</i>	1	\$ 70.00	+
10	SUNDRIES <i>x nn</i>		\$ 300.00	X
TOTAL SPARE PARTS		:	\$ 3,697.00	
TOTAL LABOUR CHARGES		:	\$ 3,152.00	
GRAND TOTAL		:	\$ 6,849.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Li*
SURVEYED DATE : *16/09/24*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: