



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0680/2024/KS
DATE : 16-Sep-24
WIP : 30928

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 17/9/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Hi Adrian,

3 Days - OK - Allan Boo

27-Nov-24

OWNER'S NAME : MR. ONG YONG WEN (WONG YONGWEN)
ADDRESS : BLK 36 YUNNAN WALK 2
SINGAPORE 638167
TELEPHONE : HP +65 98475672
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7230114772
VEHICLE NO : **SMA 7308 H**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI
MODEL YEAR : 29/11/2023
ENGINE NO : DLA E21699
CHASSIS NO : WAUZZZGY3NA101111
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Sep-24
PLACE OF ACCIDENT : NEAR 923 JURONG WEST STREET 92, BLK 923
SINGAPORE 640923

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 7308 H.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	\$ 360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,400.00	\$ 500.00
3	TO RESPRAY REAR BUMPER.	\$	1,100.00	\$ 550.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	\$ 292.00
TOTAL LABOUR CHARGES		:	\$ 3,152.00	\$ 1,702.00



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 7308 H.

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER	1	\$ 1,894.00	\$	1,515.20
2	REAR BUMPER LOCKING MECHANISM - LH / RH	2	\$ 36.00		
3	REAR BUMPER TRIM - LH	1	\$ 81.00	\$	64.08
4	REAR PARKING AID SENSOR SUPPORT - LH OUTER	1	\$ 32.00		
5	REAR BUMPER AIR GUIDE GRILLE SENSOR - LH	1	\$ 300.00		
6	REAR BUMPER SPOILER	1	\$ 254.00	\$	202.80
7	REAR LIGHT REFLECTOR - LH	1	\$ 41.00		
8	REAR BUMPER REINFORCEMENT BEAM	1	\$ 689.00		
9	REAR BUMPER GUIDE SECTION - LH	1	\$ 70.00		
10	SUNDRIES		\$ 300.00		
TOTAL SPARE PARTS		:	\$ 3,697.00	\$	1,782.08
TOTAL LABOUR CHARGES		:	\$ 3,152.00	\$	1,702.00
GRAND TOTAL		:	\$ 6,849.00	\$	3,484.08

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT