

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 08102600F

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE SKZ8013T

Not Withheld
11 Sep @ 3400h
Manny After Paint
5day

No. Qty

Nett Items

1	1	Rear bumper	\$ Bu	571.80	✓
2	2	Rear bumper side reflector	\$ Sn	170.80	X
3	2	Rear bumper side retainer	\$ Sn	96.00	X
4	1 set	Rear bumper clips	\$ M	50.00	✓
5	2	Rear corner cover	\$ Bn	345.60	X
6	2	Rear corner cover retainer	\$ In	72.00	X
7	1	Rear tailgate	\$ Bn	1,290.00	✓
8	1	Rear tailgate LH "VEZEL" emblem	\$ M	48.00	✓
9	1	Rear tailgate top lock	\$ Rd	121.00	✓
10	1	Rear tailgate lower lock catch	\$ R	34.00	X
11	1	Rear tailgate weatherstrip	\$ Rd	115.60	500h
12	1	Rear tailgate inner trim board	\$ M	285.00	✓
13	1 set	Rear tailgate inner trim board clips	\$ M	60.00	✓
14	1	Rear end panel	\$ Bn	399.40	✓
15	1	Rear end panel top garnish	\$ M	192.30	✓
16	1	Rear end panel keyless sensor	\$ Rd	195.30	✓
17	1	Rear end panel buzzer	\$ In	65.70	X
18	1	Rear spare tyre top board	\$ Bn	228.70	X
19	1	Rear under splash cover	\$ CM	290.00	✓

Total \$ 4,631.20

Special Nett Items

20	1 set	Reverse sensors	\$ Short	280.00	200h
21	1 set	Reverse camera	\$ Sn	650.00	X
22	1	Rear number plate	\$ Sn	50.00	X
23	1 set	Rear windscreen sealant	\$ M	60.00	40h
24	1 set	Rear end panel sealant	\$	60.00	30h

Acknowledged by Repairer

Signature:

Date:

Total : \$ 1,100.00

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$	1,000.00	600h
2	To putty and spray Spray Paintings charges.	\$	1,000.00	400h
3	To check wirings and lightings.	\$	40.00	20h
4	To remove, refit rear windscreen glass.	\$	140.00	120h
5	To remove, refit reverse sensors & reverse camera.	\$	150.00	80h
6	To remove, refit tailgate fittings.	\$	80.00	80h
7	To remove, refit rear upholstery and attachments.	\$	120.00	80h
8	To supply and apply anti rust treatment	\$	80.00	80h

Total : \$ 2,610.00

Total Parts and Labour : \$ 8,341.20