



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS UNITED OVERSEAS INSURANCE LTD
146 ROBINSON ROAD
#02-01 UOI BUILDING SINGAPORE 068909

Ref: CS/UOI24090259/Tvp3e2

Date: 26/09/2024

Code: UOI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 9220S	Veh. Inspected	SHC 1850X
Policy No.	-	Coverage	0
Claim No.	M11D00202409	Excess	\$0.00
Assign From	JOEY TAY	Assign Date	16/09/2024

2. Vehicle Details

Make & Model	HYUNDAI IONIQ	C.C	1580
Engine No.	G4LEKU402398	Year of Reg.	07/11/2019
Chassis No.	KMHC851CVLU188055	Colour	BLUE
Odometer	433038 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65 R15	WEST LAKE	6
L/H Front Tyre	195/65 R15	WEST LAKE	6
R/H Rear Tyre	195/65 R15	WEST LAKE	6
L/H Rear Tyre	195/65 R15	WEST LAKE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/09/2024	Inspection Date	16/09/2024
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days