



Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 S737896
HP: 93911482

Make / Model: TOYOTA NOAH

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	REAR BUMPER <i>Bu</i>	1	\$ 798.20	\$ 798.20
2	REAR BUMPER SIDE RETAINER <i>Sn</i>	2	\$ 171.45	\$ 324.40
3	REAR BUMPER TOWING COVER <i>Sn</i>	1	\$ 45.00	\$ 45.00
5	TAILGATE <i>1812.70 Bu</i>	1	\$ 2,110.25	\$ 2,110.25
6	TAILGATE INNER TRIM <i>mg mlt Bu</i>	1	\$ 589.00	\$ 589.00
7	TAILGATE "HYBRID SYNERGY DRIVE LOGO" <i>mg</i>	1	\$ 141.10	\$ 141.10
8	<i>37540</i> TAILGATE WEATHERSTRIPE <i>net</i>	1	\$ 391.05	\$ 391.05
9	TAILGATE LOCK <i>RS</i>	1	\$ 512.00	\$ 512.00
10	<i>185.80</i> TAILGATE WINDSCREEN MOULDING (SET) <i>mg</i>	1	\$ 387.00	\$ 387.00
11	TAILGATE DETECTOR <i>Sn</i>	1	\$ 287.00	\$ 287.00
12	TAILGATE BUZZER <i>Sn</i>	1	\$ 198.00	\$ 198.00
13	TAILAMP LOWER GARNISH <i>Sn</i>	2	\$ 398.00	\$ 796.00
14	REAR FENDER INNER TRIM <i>Sn</i>	2	\$ 1,124.00	\$ 2,248.00
15	REAR END PANEL (OUTER) <i>Btl Bu</i>	1	\$ 689.20	\$ 689.20
16	REAR END PANEL (INNER) <i>Sn</i>	1	\$ 685.00	\$ 685.00
17	<i>168.20</i> REAR END PANEL TOP GARNISH <i>mg o.i</i>	1	\$ 391.45	\$ 391.45
18	REAR FLOOR PANEL <i>RS</i>	1	\$ 2,489.00	\$ 2,489.00
19	REAR FLOOR PANEL TOP BOARD SET <i>Sn</i>	1	\$ 1,241.00	\$ 1,241.00
20	REAR FLOOR PANEL TOP TOOLS GARNISH <i>Sn</i>	1	\$ 412.00	\$ 412.00
	TOTAL PART			\$ 14,734.65
	LIST DOWN	25%		\$ 3,683.66
	AFTER LIST DOWN			\$ 11,050.99
	S/N			
1	REAR NUMBER PLATE <i>Sn</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER REVERSE SENSOR <i>Sn</i>	1	\$ 220.00	\$ 220.00
3	REAR BUMPER CLIP <i>mg</i>	1	\$ 50.00	\$ 50.00
4	TAILAGTE WINDSCREEN SEALANT <i>mg</i>	1	\$ 80.00	\$ 80.00
5	TAILAGTE WINDSCREEN INNER SEAL <i>mg</i>	1	\$ 80.00	\$ 80.00
6	TAILGATE INNER TRIM BOARD CLIPS SET <i>mg</i>	1	\$ 50.00	\$ 50.00
7	REAR FENDER INNER TRIM BOARD CLIP SET <i>mg</i>	2	\$ 50.00	\$ 100.00
8	REAR END PANEL SEALANT <i>mg</i>	1	\$ 120.00	\$ 120.00
9	REAR END PANEL TOP GARNISH CLIP <i>Sn</i>	1	\$ 30.00	\$ 30.00
10	REAR TOP MAT <i>Sn</i>	1	\$ 300.00	\$ 300.00
	TOTAL SPECIAL NETT			\$ 1,080.00
	Labour to: REAR			
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	1	\$ 300.00	\$ 300.00
2	CHECK AND RESET FAULT CODE LIGHT ON HYBRID BATTERY	1	\$ 500.00	\$ 500.00
3	REMOVE AND REFIT REAR WINDSCREEN GLASS <i>Repair</i>	1	\$ 150.00	\$ 150.00
4	REMOVE AND REFIT REAR SEAT ,UPHOLTERY	1	\$ 300.00	\$ 300.00

Not Notained
11 Pm @ 4200p
Pneumy After Pain
3 days