

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 53373462B

Vehicle Number : SBN5454T
Vehicle Model : TOYOTA SIENTA 1.5 CVT
Accident Date : 11.09.2024
Original Reg Date : 01.03.2023

Date : 12.09.2024
Chassis : NSP1707295107
TP Ins. AIG

ESTIMATE

1	1 pc	Bonnet			1,544.70	+
2	1 pc	Bonnet Insulator			425.60	+
3	1 set	Bonnet Insulator Clips			40.00	+
4	1 pc	Bonnet Inner Rubber			52.30	+
5	1 pc	Bonnet Inner Lock			145.30	+
6	1 pc	Front brace panel			328.20	+
7	1 pc	Front Bumper			723.30	✓
8	2 pcs	Front Bumper Side Retainers	95.60		191.20	+
9	1 set	Front Bumper Clips			50.00	30
10	1 pc	Front Bumper Reinforcement			615.90	+
11	1 pc	Front Bumper Sponge			245.90	✓
12	1 pc	Front Bumper inner top brace panel			342.90	✓
13	1 pc	Front Grille			1,346.60	✓
14	2 pc	Front Radiator Grille Side Molding	232.10		464.20	+
15	1 pc	Front Grille Retainer	76.90		153.80	+
16	2 pcs	Front Bumper Lower Side Grille	98.60		197.20	+ 98.60
17	2 pcs	Front Bumper Fog Lamp Cover	169.60		339.20	169.60
18	2 pcs	Front Fog Lamp Mounting	102.00		204.00	+
19	1 pc	Front Radiator Support Opening Garnish			203.70	+
21	1 pc	Front Bumper engine lower cover			316.90	✓
22	1 pc	Wiring Harness			1,144.80	+
23	2 pcs	Headlamps LED	3,985.50		7,971.00	✓
24	2 pcs	Headlamps top panel	256.90		513.80	+
25	2 set	Headlamps Clips	30.00		60.00	+
26	1 pc	Front washer tank			267.60	✓
27	1 pc	Front washer tank motor			185.60	+
28	2 pc	Front fender	687.80		1,375.60	+
29	2 pc	Front fender inner cowling	221.90		443.80	221.90
30	1 pc	Support Panel Assy			1,629.30	+
				subtotal	21,522.40	
				Less 25%	5,380.60	
				Total	16,141.80	

Special Nett

1	1 set	Front Number Plate with Cover <i>new</i>		50.00	+
1	1 set	Front Grille (Carbon) <i>new</i>		120.00	+
1	1 set	Front Konard Set <i>new</i>		450.00	200
2	1 set	Radiator Coolant <i>new</i>		60.00	+

Labour charge

Panel Beating		2,600.00	400
Spray painting		2,200.00	200
Check Wiring on headlamps and focussing		200.00	30
Anti rust		180.00	+
Rest Ecu And Cablibration		250.00	+
To repair and realign front chassis member		380.00	+

total 22,631.80

Adrian C.
R/S 12/09/24.
03 Days