

HONG AUTO SERVICES

2 Kaki Bukit Ave 2, #01-28, Singapore 417921
Tel: 6747 6436 / Fax: 6746 8868 / HP: 9853 5155
Email: tchong4281@gmail.com

Not Authorized
Rkh
mem.S
23/9/24
P/P @ 500/
2 day r.
Tchong Hee -

Vehicle number: SLS9698K

Vehicle Made & Model: MERCEDES-BENZ E250

Qty	List Items	Amount \$
1	Rear bumper	R 2,332.21 X
1	Rear bumper PDC sensor - RH	su 276.33 X
1	Rear sport wheel	R 1,655.90 X
1	Rear wheel hub bearing	su 561.95 X
Sub-total		4,826.39
Less 10%		482.64
Total List		4,343.75

Labour Charges

To respray painting & etc	600.00 400
Panel beating, cut, weld, remove & replacing above parts	600.00 100
Total Labour	1,200.00

ESTIMATE PARTS & LABOUR GRAND TOTAL \$

5,543.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: