

26	REAR FLOOR PANEL TOP BORD <i>neu</i>	1	\$ 597.00	\$ 597.00	+
27	REAR EXHAUST BOX WITH CHROME PIPE <i>But</i>	1	\$ 2,894.00	\$ 2,894.00	+
28	REAR EXHAUST INSULATOR <i>tom</i>	1	\$ 196.00	\$ 196.00	-
29	REAR EXHAUST MOUNTING <i>neu</i>	4	\$ 97.00	\$ 388.00	+
30	REVERSE SENSOR <i>neu</i>	4	\$ 298.00	\$ 1,192.00	+
31	REVERSE SENSOR HOLDER <i>neu</i>	4	\$ 64.00	\$ 256.00	+

1257

TOTAL PRICE \$ 20,104.90
 LESS 10% \$ 2,010.49
 SUB TOTAL PRICE \$ 18,094.41

8175.30

7357.77

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE WITH CASING (SEPCIAL) <i>neu</i>	1	\$ 100.00	\$ 100.00	+
2	REAR BUMPER CLIP (SET) <i>neu</i>	1	\$ 50.00	\$ 50.00	30
3	BOOTLID INSULATOR CLIP (SET) <i>neu</i>	1	\$ 50.00	\$ 50.00	+
4	BOOTLID MOULDING CLIP (SET) <i>neu</i>	1	\$ 30.00	\$ 30.00	+
5	BOOTLID CYCLE AND CARRIAGE EMBLEM <i>neu</i>	1	\$ 80.00	\$ 80.00	95
6	TAILLAMP CLIPS (SET) <i>neu</i>	1	\$ 30.00	\$ 30.00	+
7	REAR FENDER TOP GARNISH CLIP (SET) <i>neu</i>	1	\$ 30.00	\$ 30.00	+
8	REAR FENDER COWLING CLIPS (SET) <i>neu</i>	1	\$ 50.00	\$ 50.00	+
9	REAR FENDER INNER TRIM CLIPS (SET) <i>neu</i>	1	\$ 50.00	\$ 50.00	+
10	REAR FENDER VINYL WRAP <i>neu</i>	1	\$ 900.00	\$ 900.00	+
11	REAR BUMPER VINYL WRAP <i>neu</i>	1	\$ 700.00	\$ 700.00	250 250
12	BOOTLID VINYL WRAP <i>neu</i>	1	\$ 800.00	\$ 800.00	250 250
13	REAR END PANEL SEALANT <i>neu</i>	1	\$ 150.00	\$ 150.00	60
14	REAR END PANEL TOP GARNISH CLIPS (SET) <i>neu</i>	1	\$ 30.00	\$ 30.00	20
15	REAR FLOOR PANEL (FIBRE) SEALANT <i>neu</i>	1	\$ 250.00	\$ 250.00	+
TOTAL				\$ 3,350.00	

655

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00	800
3	TUFF COAT	\$ 200.00	60
4	WIRING CHECK ON TAILAMP	\$ 60.00	30
5	REMOVE AND REFIX INTERIOR UPHOLSTRY TO FACILITATE REPAIR	\$ 150.00	60
6	TRANFER BOOTLID MECHANISM	\$ 80.00	x
7	CONDUCT WATER LEAKAGE TEST	\$ 60.00	x
8	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 150.00	60
9	REAR CHASSIS ALIGNMENT	\$ 180.00	x
10	RESET HEADREST	\$ 300.00	x
11	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00	x

1860

TOTAL

5510

TOTAL PARTS COST : \$ 21,444.41
 TOTAL LABOUR COST : \$ 5,510.00
 TOTAL REPAIR COST : \$ 26,954.41

Adrian G

K/S 16/09/24.

OT Dmg

total: 9822.77

L/S: 7.8K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature:
 Date:

08 Dmg

7.8K