

SUPER-ZEE MOTOR SERVICE

BLK 14 DEFU LANE 10 #01-402 SINGAPORE 539195 TEL: 6383 1913 FAX: 6383 9565
EMAIL: superzeemotor@gmail.com

16 Sep 2024

ECICS Ltd
10 Eunus Road 8 #09-04A
Singapore Post Centre
Singapore 408600
Att: Motor Claims Dept

Not Authorized
for
work
20/9/24
4/5 H 750/
2 days.
Zeh ph. Atkney

THIRD PARTY CLAIM

OWNER NAME : LIM YEN MEI AMANDA
VEHICLE REG NO : SMH8304A
DATE OF ACCIDENT : 11 SEP 2024
PLACE OF ACCIDENT : ANCHORVALE LINK CARPARK (SK52)
INVOLVING VEH NO : SKW4582J

We append herewith our estimate for the repair of SMH8304A as follows:

Materials Required

1 pc	Rear Bumper	17	S\$	650.80	X
1 pc	Rear Bumper Retainer RH	17	S\$	32.40	X
1 pc	Rear Bumper Corner Side RH	cut/2c	S\$	218.40	✓
10 pcs	Rear Bumper Clips	17	S\$	65.00	X
1 pc	Rear Fender Arch RH	cut	S\$	236.90	✓
1 pc	Rear Fender Inner Shield RH	17	S\$	160.20	X
1 pc	Rear Tyre Rim RH	11c cut	S\$	450.00SN	X
1 pc	Rear Tyre RH	17	S\$	300.00SN	X
				202	
				S\$2,113.70	

Labour Charges

To dismantle & replace damaged parts, panelbeat where necessary	S\$	550.00	200
To putty, apply primer & spraypaint affected portion	S\$	600.00	400
To apply rustproofing on repaired, replaced panel	17	S\$	180.00
			X
		S\$3,443.70	

SUPER-ZEE MOTOR SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) for survey
- All prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Business Registration No.47959700J