

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/P 91082728

Focus Toh
Blk 697 Hougang St 61
#11-24
Singapore 530697

Vehicle No : SMP 7601 G
Make/Model : Honda Shuttle
Year : 2019

Not Withheld
11 Sep @ 3300h
Resurvey After Paint
4 days

| Qty | Description | Unit Price | Amount |
|-----|-------------|------------|--------|
|-----|-------------|------------|--------|

Estimate Cost Of Repair

| | | |
|-------|-------------------------------------|---------|
| 1 pc | Rear tail-gate assy | 1193.70 |
| 1 pc | Rear tail-gate glass moulding | |
| 1 pc | Rear tail-gate emblem " Shuttle " | |
| 1 pc | Rear tail-gate emblem " Hybrid " | |
| 1 pc | Rear tail-gate emblem " H " | |
| 1 pc | Rear tail-gate outer chrome garnish | |
| 1 pc | Rear tail-gate inner lock | |
| 1 pc | Rear tail-gate inner trim board | |
| 2 pcs | Rear tail-gate reflector | |
| 1 pc | Rear boot rubber | |
| 1 pc | Rear end panel | |
| 1 pc | Rear end panel inner garnish | |
| 1 pc | Rear bumper | |
| 2 pcs | Rear bumper side retainer | |

| | | |
|-----------|------------|------------|
| Pr | \$1,281.10 | / |
| me | \$105.20 | / |
| me | \$65.10 | / |
| me | \$57.20 | / |
| me | \$40.10 | / |
| in | \$385.70 | X |
| me | \$305.10 | / |
| me | \$287.40 | / |
| \$420.10 | \$840.20 | X |
| Dis Ind | \$195.70 | 50% 97.85% |
| R | \$588.60 | X |
| in | \$185.90 | / |
| me | \$965.70 | / |
| \$38.20 | \$76.40 | X |
| | \$5,379.40 | |
| Less 20 % | \$1,075.88 | |
| | \$4,303.52 | |

S Net

| | |
|--------|------------------------------|
| 1 pc | Rear reverse sensor |
| 1 pc | Rear tail-gate glass sealant |
| 20 pcs | Rear bumper clip |
| 1 pc | Rear no plate |

| | | |
|----------|----------|-----|
| Scr/shot | \$200.00 | / |
| me | \$55.00 | 40% |
| me | \$40.00 | / |
| in | \$40.00 | X |
| | \$335.00 | |

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

To putty and spray paint

| | | |
|-------------|------------|-----|
| | \$1,000.00 | 50% |
| | \$1,000.00 | 60% |
| balance c/f | \$6,638.52 | |

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SMP 7601 G

balance b/f \$6,638.52

Labour Charges

Check & reconnect wiring.

\$45.00 201

To respray anti-rust proofing treatment

\$120.00 301

Remove/refit rear windscreen to facilitate repair

\$120.00 ✓

Remove/refit rear tail-gate mechanism to new door.

\$150.00 601

Remove/refit rear boot upholstery to facilitate repair.

\$100.00

Total

\$7,173.52