

REF: CS/AGI24090281/Anp3 (SMM 3881G)

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimate: \_\_\_\_\_

OD / TP / TP RES / CD RES / EVA / INV / MV

To in \_\_\_\_\_ vehicle No: \_\_\_\_\_

at \_\_\_\_\_ km/s

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claim No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: There had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repair: 2 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SMM3881G Yr Regn: 2018 JuneType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Cerato C.D. 1591Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 114174 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNAF3416MK-5045976Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18R: 225/40R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal. 06 mmL/Bal. 06 mm

D.O.A. \_\_\_\_\_

Rear

R/Bal. 06 mmL/Bal. 06 mmD.O.I. 16/09/24Survey held at KT Motorwerk

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rees ops.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Budget DirectCOE ExpiryEstimate given during : Yes (✓)  
1st Survey : No (✓)

MV :

PV :

Nett :

**Adrian confirmed lump sum \$950 and 2 day  
(red, \$11937.63, 92%)**686D

Date/Time, File Pass to?



Preli. Report



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:



Site Insp (\$



Interview (\$



Tech. Inve (\$

Survey Fee:

Transportation:

S + RS. \$1

Photos

Others

Report Format:

Report 2 Form / 1 P. 10



# 國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.  
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177  
Email: ktmotorwerk@hotmail.com  
Reg. No.: 53373462B

## VEHICLE REPAIR ESTIMATE

Vehicle Number : SMM3881G

Date : 14.09.2024

Vehicle Model : KIA CERATO K3

Chassis : KNAF3416MK50459  
76

Accident Date : 12.09.2024

TP Ins. BUDGET DIRECT

Original Reg Date : 27.06.2019

### ESTIMATE

11	1 pc	TAILAMP	698.50	698.50	+
12	1 pc	TAILAMP PANELS	298.70	298.70	+
13	1 pcs	TAILAMP INNER SEALER	35.00	35.00	+
14	1 pcs	REAR BUMPER		985.90	+
15	1 pcs	REAR BUMPER SMART KEY SENSOR		275.30	+
16	1 pcs	REAR LOWER BUMPER		485.80	+
17	2 pcs	REAR BUMPER RETAINERS	158.30	316.60	+
18	1 pcs	REAR BUMPER LOWER COVER	168.20	336.40	+
21	1 pc	REAR BUMPER REINFORCEMENT		627.50	+
22	2 pc	REAR REINFORCEMENT TOP BRACKETS	98.90	197.80	+
23	3 pc	REAR REINFORCEMENT BOTTOM BRACKETS	94.50	283.50	+
24	2 pc	REAR BUMPER SENSORS	285.80	571.60	+
26	1 pc	REAR FENDER		1,425.30	+
26	1 pc	REAR FENDER AIR DUCT RH		185.20	+
27	1 pc	REAR FENDER INNERTRIM	334.60	334.60	+
28	1 pc	REAR FENDER INNERSHIELD	195.80	195.80	+
30	1 pc	END PANEL		495.80	+
31	1 pc	END PANEL TOP GARNISH		214.60	+
32	1 pc	END PANEL SMART KEY ANTENNA(INNER)		266.80	+

subtotal 8,230.70

less 10% 823.07

total 7,407.63

### Special Nett

1	1 set	Rear Number Plate with Holder	50.00	+
2	1 set	Tailamps clips	30.00	+
3	1 set	Rear Bumper Diffuser (Speical)	950.00	+
4	1 set	Rear Bumper Side Skirt Lip RH (Speical)	350.00	+
5	1 PC	Rims	950.00	+
6	1 PC	Tyre	280.00	+
7	1 set	Rear fender inner trim clips	30.00	+
8	1 set	Rear fender inner shield clips	30.00	+

9	1 set	Body Panel Joint Sealant <i>HP m</i>		120.00	<i>+</i>
---	-------	--------------------------------------	--	--------	----------

### Labour charge

Panel Beating		1,000.00	<i>20</i>
Spray painting		1,000.00	<i>20</i>
Check Wiring on tailamps		120.00	<i>+</i>
Anti rust		180.00	<i>+</i>
4 Wheel Aightment		150.00	<i>+</i>
Remove and install reverse sensor		120.00	<i>50</i>
Remove and install interior upholstery		120.00	<i>+</i>
		<b>\$ 12,887.63</b>	

*Adrian Lij*  
*2/s 16/09/24*  
*02 Days*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: