



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS SOMPO INSURANCE SINGAPORE PL	Ref:	CS/SMO24090283/Unp3
50 RAFFLES PLACE #03-03	Date:	27/09/2024
SINGAPORE LAND TOWER SINGAPORE 048623	Code:	SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 566D	Veh. Inspected	SBP 6331Y
Policy No.	D24MTPCVE001715	Coverage	0
Claim No.	CMTD2402957/GPL	Excess	\$0.00
Assign From	GNOH PAU LOONG	Assign Date	17/09/2024

2. Vehicle Details

Make & Model	SUBARU IMPREZA 5D 2.5 WRX-S AWD 5MT	C.C	2457
Engine No.	EJ25D362606	Year of Reg.	14/05/2009
Chassis No.	JF1GHEKD38G015133	Colour	BLACK
Odometer	229067 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/40R18	YOKOHAMA	6
L/H Front Tyre	225/40R18	YOKOHAMA	6
R/H Rear Tyre	225/40R18	YOKOHAMA	6
L/H Rear Tyre	225/40R18	YOKOHAMA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/09/2024	Inspection Date	18/09/2024
Survey held at	2ND AUTO PTE LTD 15 KAKI BUKIT ROAD 4, #01-53, BARTLEY BIZ CENTRE, SINGAPORE 417808		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days