

2ND AUTO PTE LTD

15 Kaki Bukit Road 4 #01-53 Bartley Bizcentre Singapore 417808

Main Line : (65) 6741 6741

Fax : 6746 7939

Vehicle Reg No. : SBP 6331 Y
Model : SUBARU IMPREZA WRX

Not Authorized
18/9/24

1/5 # 3500
take photo after repair
4 days

16-Sep-24

Estimated repair cost for the vehicle as mentioned above

Qty	Description	Amt S(\$)
<u>List Items</u>		
2	Front headlamps n/s n10/s cr	\$ 3,960.00 1280
2	Front headlamp panels	\$ 231.00
2	Front headlamp lower brackets	\$ 283.40
2	Front bumper fog lamps	\$ 962.80
2	Front bumper fog lamp covers	\$ 396.20
2	Front bumper side retainers	\$ 99.60
1	Front bumper nozzle cover	\$ 80.60
2	Front fender inner shields	\$ 220.60
1	Front support panel	\$ 625.50
1	Front brace panel	\$ 78.50
		\$ 6,938.20
	Less 10% 202	\$ 693.82
		\$ 6,244.38

Special Nett Items

1	Front bonnet -Carbon fibre	\$ 2,500.00 1200
1	Front grille assy	\$ 450.00
1	Front bumper -Carbon fibre	\$ 2,000.00 820
1	Front bumper clip (1 set)	\$ 80.00 30
1	Front number plate with holder -Carbon fibre	\$ 180.00 40
1	Front fender -RH	\$ 1,250.00
		\$ 6,460.00

S/N LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$ 80.00 20
2	Panel beating.	\$ 1,800.00 300
3	To re-spray painting on the affected areas.	\$ 1,600.00 550
		\$ 3,480.00

Grand Total : P-1480 202
P-1024
S.M-2520
L-870
\$ 16,184.38