

2ND AUTO PTE LTD

15 Kaki Bukit Road 4 #01-53 Bartley Bizcentre Singapore 417808

Main Line : (65) 6741 6741

Fax : 6746 7939

LKK Auto Consultants hence notify

the Repairer of the following

to carry out repair and painting

of damaged parts, etc.

Parts prices are subject to confirmation

of third party survey is done.

No illegal modification(s) is allowed

Supplementary item(s) must be 16-Sep-24
is subject to final approval from Insurance Company

Not Authorized

18/9/24

1/5 H 3500

Chk photo Hk up

4 days

Vehicle Reg No. : SBP 6331 Y

Model : SUBARU IMPREZA WRX

Estimated repair cost for the vehicle as mentioned above

Qty	Description	Amt S(\$)
<u>List Items</u>		
2	Front headlamps N/S 110/5 cm 1280	\$ 3,960.00 PC
2	Front headlamp panels R	\$ 231.00 X
2	Front headlamp lower brackets 11	\$ 283.40 X
2	Front bumper fog lamps 11	\$ 962.80 X
2	Front bumper fog lamp covers 11	\$ 396.20 X
2	Front bumper side retainers 11	\$ 99.60 X
1	Front bumper nozzle cover 11	\$ 80.60 X
2	Front fender inner shields 11	\$ 220.60 X
1	Front support panel R	\$ 625.50 X
1	Front brace panel 11	\$ 78.50 X
		\$ 6,938.20
	Less 10% 202	\$ 693.82
		\$ 6,244.38

Special Nett Items

1	Front bonnet -Carbon fibre CNE	\$ 2,500.00 1200
1	Front grille assy CNE	\$ 450.00 ✓
1	Front bumper -Carbon fibre 00/15.11	\$ 2,000.00 800
1	Front bumper clip (1 set) net	\$ 80.00 30
1	Front number plate with holder -Carbon fibre Daye	\$ 180.00 40
1	Front fender -RH 11	\$ 1,250.00 X
		\$ 6,460.00

S/N

LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$ 80.00 20
2	Panel beating.	\$ 1,800.00 300
3	To re-spray painting on the affected areas.	\$ 1,600.00 550
		\$ 3,480.00

Grand Total : P-1180
202

\$ 16,184.38

P-1024

S.A. 2520

L-870