


Company Reg No: 202136904Z

Tel : 6341 6789 Fax: 6341 6778
E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 06.12.2024

TO : **CHINA TAIPING** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNN3747U**
MODEL : **VOLKSWAGEN JETTA**
DATE OF ACCIDENT : 05.12.2024
TIME OF ACCIDENT : 20:05 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL - PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Crushed</i>	1	\$ 1,387.50	\$ 1,387.50
2	FRONT BUMPER SIDE RETAINER <i>Crushed</i>	2	\$ 124.20	\$ 248.40
3	FRONT BUMPER NOZZLER LH <i>Ren</i>	1	\$ 285.30	\$ 285.30
4	FRONT BUMPER NOZZLER COVER LH <i>Ren</i>	1	\$ 78.60	\$ 78.60
5	FRONT BUMPER PARKING SENSOR LH <i>Ren</i>	1	\$ 451.20	\$ 451.20
6	FRONT BUMPER PARKING SENSOR HOLDER <i>Ren</i>	2	\$ 78.00	\$ 156.00
7	FRONT BUMPER FOG LAMP LH <i>Crushed</i>	1	\$ 385.00	\$ 385.00
8	FRONT BUMPER FOG LAMP COVER LH <i>lit</i>	1	\$ 188.00	\$ 188.00
9	FRONT BUMPER FOG LAMP LOWER GARNISH L <i>Ren</i>	1	\$ 196.00	\$ 196.00
10	FRONT BUMPER SPONGE <i>Crushed</i>	1	\$ 198.20	\$ 198.20
11	FRONT GRILLE C/W CHROME <i>Ren</i>	1	\$ 2,473.77	\$ 2,473.77
12	FRONT GRILLE LOGO <i>Ren</i>	1	\$ 169.81	\$ 169.81
13	HEADLAMP LH <i>Crushed</i>	1	\$ 2,864.30	\$ 2,864.30
14	HEADLAMP BRACKET LH <i>Ren</i>	1	\$ 58.69	\$ 58.69
15	FRONT FENDER LH <i>Dented</i>	1	\$ 695.77	\$ 695.77
16	FRONT FENDER SUPPORT BRACKET LH <i>Not Best</i>	1	\$ 185.20	\$ 185.20
17	FRONT FENDER INNER COWLING LH <i>ton</i>	1	\$ 233.97	\$ 233.97
18	FRONT WHEEL RIM LH <i>lit</i>	1	\$ 1,680.00	\$ 1,680.00
19	FRONT ABS SENSOR LH <i>Ren</i>	1	\$ 195.33	\$ 195.33

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SNN3747U
 MODEL : VOLKSWAGEN JETTA
 DATE OF ACCIDENT : 05.12.2024
 TIME OF ACCIDENT : 20:05 HOURS

20	FRONT STEERING RACK AND PINION <i>new</i>	1	\$ 4,380.89	\$ 4,380.89	<i>+</i>
21	FRONT KNUCKLE ARM LH <i>?</i>	1	\$ 870.99	\$ 870.99	<i>?</i>
22	FRONT KNUCKLE ARM BEARING LH <i>?</i>	1	\$ 531.60	\$ 531.60	<i>?</i>
23	FRONT LOWER ARM LH <i>?</i>	1	\$ 560.70	\$ 560.70	<i>?</i>
24	FRONT STABILIZER BAR LINKAGE LH <i>new</i>	1	\$ 138.70	\$ 138.70	<i>+</i>
25	DRIVE SHAFT LH <i>new</i>	1	\$ 2,400.71	\$ 2,400.71	<i>+</i>
26	FRONT SHOCK ABSORBER LH <i>new</i>	1	\$ 764.80	\$ 764.80	<i>+</i>

TOTAL PRICE \$ 21,779.43
 LESS 10% \$ 2,177.94
SUB TOTAL PRICE \$ 19,601.49

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
2	FRONT BUMPER UNDER COVER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
3	FRONT GRILLE (UPPER) CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
4	FRONT FENDER INNER COWLING CLIP RH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
5	FRONT WHEEL TYRE RH <i>new</i>	1	\$ 480.00	\$ 480.00	<i>+</i>
6	WHEEL CAP (SET) <i>new</i>	1	\$ 100.00	\$ 100.00	<i>+</i>
7	BRAKE OIL <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>

TOTAL \$ 870.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	<i>500</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	<i>400</i>
3	TUFF COAT	\$ 250.00	<i>+</i>
4	WIRING CHECK	\$ 80.00	<i>30</i>
5	REFOCUS HEADLAMP BEAM	\$ 80.00	<i>+</i>
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	<i>?</i>

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SNN3747U
MODEL : VOLKSWAGEN JETTA
DATE OF ACCIDENT : 05.12.2024
TIME OF ACCIDENT : 20:05 HOURS

7	FOUR WHEEL ALIGNMNET	\$ 120.00	80
8	REMOVE AND REFIXFRONT BUMPER SENSOR AND DISTANCE SETTING	\$ 180.00	50
9	RESET ABS LIGHT	\$ 350.00	x
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 650.00	x

TOTAL \$4,560.00

TOTAL PARTS COST : \$ 20,471.49
TOTAL LABOUR COST : \$ 4,560.00
TOTAL REPAIR COST : \$ 25,031.49

Adrian Li
2/8 06/12/24.
06 days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: