


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 16.09.2024

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNN3747U**
MODEL : **VOLKSWAGEN JETTA**
DATE OF ACCIDENT : 15.09.2024
TIME OF ACCIDENT : 08:45 HOURS

Xiao Chen.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>tom</i>	1	\$ 1,387.50	\$ 1,387.50
2	FRONT BUMPER FOG LAMP LH <i>2x</i>	1	\$ 385.00	\$ 385.00
3	FRONT BUMPER FOG LAMP COVER LH <i>1x</i>	1	\$ 188.00	\$ 188.00
4	FRONT BUMPER FOG LAMP LOWER GARNISH LH <i>1x</i>	1	\$ 196.00	\$ 196.00
5	FRONT BUMPER SPONGE <i>New</i>	1	\$ 198.20	\$ 198.20
6	HEADLAMP LH <i>New</i>	1	\$ 2,864.30	\$ 2,864.30
7	FRONT FENDER INNER COWLING LH <i>New</i>	1	\$ 233.97	\$ 233.97
8	FRONT WHEEL RIM LH <i>1x</i>	1	\$ 1,680.00	\$ 1,680.00
9	FRONT ABS SENSOR LH <i>New</i>	1	\$ 195.33	\$ 195.33
10	FRONT STEERING RACK AND PINION <i>New</i>	1	\$ 4,380.89	\$ 4,380.89
11	FRONT KNUCKLE ARM LH <i>Repl</i>	1	\$ 870.99	\$ 870.99
12	FRONT KNUCKLE ARM BEARING LH <i>Repl</i>	1	\$ 531.60	\$ 531.60
13	FRONT LOWER ARM LH <i>Best</i>	1	\$ 560.70	\$ 560.70
14	FRONT STABILIZER BAR LINKAGE LH <i>New</i>	1	\$ 138.70	\$ 138.70
15	FRONT SHOCK ABSORBER LH <i>New</i>	1	\$ 764.80	\$ 764.80

3111.69 S.W. 800
2800.52

TOTAL PRICE \$ 14,575.98
LESS 10% \$ 1,457.60
SUB TOTAL PRICE \$ 13,118.38

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00
2	FRONT BUMPER UNDER COVER CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNN3747U**
 MODEL : **VOLKSWAGEN JETTA**
 DATE OF ACCIDENT : 15.09.2024
 TIME OF ACCIDENT : 08:45 HOURS

3	FRONT GRILLE (UPPER) CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
4	FRONT FENDER INNER COWLING CLIP RH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
5	FRONT WHEEL TYRE RH <i>new</i>	1	\$ 480.00	\$ 480.00	+
6	WHEEL CAP (SET) <i>new</i>	1	\$ 100.00	\$ 100.00	+
7	BRAKE OIL <i>new</i>	1	\$ 30.00	\$ 30.00	+

30

TOTAL \$ 870.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	200
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	200
3	TUFF COAT	\$ 250.00	+
4	WIRING CHECK	\$ 80.00	30
5	REFOCUS HEADLAMP BEAM	\$ 80.00	+
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	20
7	FOUR WHEEL ALIGNMENT	\$ 120.00	80
8	REMOVE AND REFIX FRONT BUMPER SENSOR AND DISTANCE SETTING	\$ 180.00	+
9	RESET ABS LIGHT	\$ 350.00	+
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 650.00	+

710

LKK Auto Consultants hence notify the Repairer **TOTAL \$4,560.00** following:
 • To resurvey before/after spray painting
 • Display damaged part(s) during resurvey
 • Prices are subject to company's "Without Police" basis
 • No illegal modification(s) is allowed
 • Any mandatory item(s) must be resurveyed and is subject to final approval by the company

TOTAL PARTS COST \$ 13,988.38
 TOTAL LABOUR COST \$ 4,560.00
 TOTAL REPAIR COST \$ 18,548.38

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

Adrian L
 2/8 17/09/24
 03 Days

total: 4340.52
 4/5: 3450