



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMJ 722T

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	DEFORMED	\$841.20	\$841.20
1	REAR BUMPER RH REFLECTOR	NOT NECESSARY	\$141.10	\$0.00
1	REAR BUMPER RH SIDE RETAINER	NOT NECESSARY	\$86.10	\$0.00
1	REAR BUMPER TOW HOOK COVER	NOT NECESSARY	\$32.10	\$0.00
1	REAR RH TAILLAMP	NOT NECESSARY	\$666.70	\$0.00
1	REAR RH TAILLAMP LOWER GARNISH	DEFORMED	\$176.80	\$176.80
1	REAR RH TAILLAMP LOWER GARNISH RETAINER	NOT NECESSARY	\$160.70	\$0.00
	LESS 25.00% DISCOUNT		(\$526.18)	(\$254.50)
			\$1,578.52	\$763.50

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	\$50.00	\$0.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	\$280.00	\$0.00
			\$330.00	\$0.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR		\$80.00	\$50.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT		\$600.00	\$300.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT		\$600.00	\$300.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	NOT NECESSARY	\$80.00	\$0.00
			\$1,360.00	\$650.00

GRAND TOTAL	\$3,268.52	\$1,413.50
--------------------	-------------------	-------------------

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	\$1,100.00
---	-------------------

Report Ref No: CS/INC24090288/Anh3m4

TOTAL FOR SPARE PARTS: \$ 1,908.52 \$ 763.50
TOTAL FOR LABOUR : \$ 1,360.00 \$ 650.00
TOTAL REPAIR COST: \$ 3,268.52 \$ 1,413.50



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.