

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact :

TP/NC
Hui Rong
TAX INVOICE

Repair Code : CLM18352

Date in : 20/08/2024

Vehicle Num. : SMJ722T

Model : TOYOTA NOAH HYBRID 7-SEATER 1.8X CVT

Chassis/Eng# : ZWR800348412/2ZR0C46883

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Behind</i>	1	841.20	841.20
REAR BUMPER RH REFLECTOR <i>ren</i>	1	141.10	+ 141.10
REAR BUMPER RH SIDE RETAINER <i>ren</i>	1	86.10	+ 86.10
REAR BUMPER TOW HOOK COVER <i>ren</i>	1	32.10	+ 32.10
REAR RH TAILLAMP <i>Not n</i>	1	666.70	+ 666.70
REAR RH TAILLAMP LOWER GARNISH <i>Behind</i>	1	176.80	176.80
REAR RH TAILLAMP LOWER GARNISH RETAINER <i>Not n</i>	1	160.70	+ 160.70
Subtotal before discount			2,104.70
Percentage discount 25%			526.18
Sub-total 1			1,578.53
REAR BUMPER CLIPS - SET <i>ren</i>	1	50.00	+ 50.00
REAR BUMPER REVERSE SENSOR - SET <i>Not n</i>	1	280.00	+ 280.00
Subtotal before discount			330.00
Percentage discount 0%			0.00
Sub-total 2			330.00
Parts-total			1,908.53

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

50 ~~80.00~~
300 ~~600.00~~

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact :

TAX INVOICE

Repair Code : CLM18352

Date in : 20/08/2024

Vehicle Num. : SMJ722T

Model : TOYOTA NOAH HYBRID 7-SEATER 1.8X CVT

Chassis/Eng# : ZWR800348412/2ZR0C46883

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

1,360.00

Parts & Labour Total

3,268.53

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Admin LJ
1/s 17/09/24

032ys.

1413.50

total: ~~1063.50~~

L/S: ~~800~~ 1.11C ✓