

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LIM WEE HWA
BLK 650 ANG MO KIO ST 61 #15-17
SINGAPORE 560650

Contact : 87220883

TP/INC
Veron.

TAX INVOICE

Repair Code : CLM16425

Date in : 14/09/2024

Vehicle Num. : SKU699T

Model : VOLKSWAGEN GOLF A7 1.2 TSI AT 5G12DZ

Chassis/Eng# : WVVZZZAUZFW332057/CJZ615695

Parts and Labour Assesment

Description of part	Qty	Unit Price	1410 Amount
FRONT BONNET <i>Dented</i>	1	4000.33	4,000.33
FRONT BONNET HINGES L/R <i>2 new</i>	2	299.69	+ 599.38
FRONT BONNET MECHANISM LOCK	1	400.30	+ 400.30
FRONT BUMPER <i>Distorted</i>	1	1690.00	1,690.00
FRONT BUMPER INNER CENTER BRACKET <i>2 new</i>	1	215.00	215.00
FRONT BUMPER LOWER GRILLE <i>2 new</i>	1	198.00	198.00
FRONT BUMPER REINFORCEMENT <i>2 new</i>	1	599.00	+ 599.00
FRONT BUMPER SIDE RETAINER L/R <i>2 new</i>	2	105.00	+ 210.00
FRONT BUMPER SPONGE <i>2 new</i>	1	189.00	189.00
FRONT GRILLE <i>2 new</i>	1	1477.55	1,477.55
FRONT GRILLE 'LOGO' EMBLEM <i>2 new</i>	1	399.89	399.89
FRONT RH FENDER INNER TRIM SIDE GARNISH <i>2 new</i>	1	2333.77	+ 2,333.77
FRONT RH HEADLAMP <i>2 new</i>	1	3250.00	3,250.00
FRONT RH HEADLAMP LOWER BRACKET <i>2 new</i>	1	156.00	+ 156.00
REAR BUMPER <i>Distorted</i>	1	1317.71	1,317.71
REAR BUMPER INNER BRACKET <i>2 new</i>	1	269.89	+ 269.89
REAR BUMPER LOWER LID <i>2 new</i>	1	399.70	+ 399.70
REAR BUMPER NUMBER PLATE LAMP L/R <i>2 new</i>	2	99.87	+ 199.74

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LIM WEE HWA
BLK 650 ANG MO KIO ST 61 #15-17
SINGAPORE 560650

Contact : 87220883

TAX INVOICE

Repair Code : CLM16425

Date in : 14/09/2024

Vehicle Num. : SKU699T

Model : VOLKSWAGEN GOLF A7 1.2 TSI AT 5G12DZ

Chassis/Eng# : WVVZZZAUZFW332057/CJZ615695

REAR BUMPER REFLECTOR L/R	<i>RH and</i>	2	180.77	<i>180.77</i>	361.54
REAR BUMPER REINFORCEMENT	<i>Defect</i>	1	600.77	<i>2</i>	600.77
REAR BUMPER SIDE RETAINER L/R	<i>new</i>	2	123.60	<i>+</i>	247.20
REAR BUMPER TOW HOOK COVER	<i>new</i>	1	100.77	<i>+</i>	100.77
REAR END PANEL	<i>Defect</i>	1	1477.51	<i>790</i>	1477.51
REAR END PANEL INNER TOP GARNISH	<i>Defect</i>	1	288.96	<i>2</i>	288.96
REAR FLOOR PANEL	<i>new</i>	1	1800.77	<i>+</i>	1,800.77
REAR FLOOR PANEL TOP BOARD COVER	<i>new</i>	1	688.96	<i>+</i>	688.96
REAR FLOOR PANEL TOP BOARD COVER SIDE GARNISH RH	<i>new</i>	1	199.31	<i>+</i>	199.31
REAR FLOOR PANEL TOP INSULATOR MAT	<i>new</i>	1	499.70	<i>+</i>	499.70
REAR RH FENDER INNER TRIM	<i>new</i>	1	611.71	<i>+</i>	611.71
REAR RH TAILLAMP	<i>new</i>	1	788.90	<i>+</i>	788.90
REAR RH TAILLAMP LOWER BRACKET	<i>new</i>	1	160.70	<i>+</i>	160.70
REAR RH TAILLAMP PANEL	<i>new</i>	1	829.70	<i>+</i>	829.70
REAR TAILGATE	<i>Defect</i>	1	2000.77	<i>✓</i>	2,000.77
REAR TAILGATE DAMPER L/R	<i>new</i>	2	190.71	<i>+</i>	381.42
REAR TAILGATE HINGES L/R	<i>new</i>	2	199.30	<i>+</i>	398.60
REAR TAILGATE INNER RUBBER SEAL	<i>new</i>	1	400.75	<i>+</i>	400.75

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LIM WEE HWA
BLK 650 ANG MO KIO ST 61 #15-17
SINGAPORE 560650

Contact : 87220883

TAX INVOICE

Repair Code : CLM16425

Date in : 14/09/2024

Vehicle Num. : SKU699T

Model : VOLKSWAGEN GOLF A7 1.2 TSI AT 5G12DZ

Chassis/Eng# : WVVZZZAUZFW332057/CJZ615695

REAR TAILGATE INNER TRIM BOARD	<i>Chkd</i>	1	699.31	<i>✓</i>	699.31
REAR TAILGATE LOCK STRIKER	<i>OK</i>	1	100.77	<i>+</i>	100.77
REAR TAILGATE MECHANISM LOCK	<i>2nd</i>	1	233.96	<i>✓</i>	233.96
REAR TAILGATE OPENER SWITCH	<i>OK</i>	1	600.33	<i>+</i>	600.33
REAR TAILGATE OPENER SWITCH 'LOGO' EMBLEM	<i>me u</i>	1	189.60	<i>+</i>	189.60
REAR TAILGATE RH REFLECTOR	<i>ut</i>	1	689.89	<i>350</i>	689.89
REAR TAILGATE WEATHER STRIP	<i>zt</i>	1	488.70	<i>✓</i>	488.70
REAR TAILGATE WINDSCREEN MOULDING	<i>me</i>	1	180.77	<i>✓</i>	180.77
Subtotal before discount					32,926.63
Percentage discount 10%					3,292.66
Sub-total 1					29,633.97
FRONT BUMPER CLIPS - SET	<i>me</i>	1	80.00	<i>30</i>	80.00
FRONT NUMBER PLATE	<i>Best</i>	1	25.00	<i>✓</i>	25.00
FRONT NUMBER PLATE HOLDER	<i>Delhd</i>	1	50.00	<i>30</i>	50.00
REAR BUMPER NUMBER PLATE	<i>Best</i>	1	25.00	<i>✓</i>	25.00
REAR BUMPER NUMBER PLATE FRAME	<i>Delhd</i>	1	50.00	<i>30</i>	50.00
REAR BUMPER REVERSE SENSOR	<i>2nd</i>	1	280.00	<i>20</i>	280.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	<i>me</i>	1	30.00	<i>20</i>	30.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LIM WEE HWA
BLK 650 ANG MO KIO ST 61 #15-17
SINGAPORE 560650

Contact : 87220883

TAX INVOICE

Repair Code : CLM16425

Date in : 14/09/2024

Vehicle Num. : SKU699T

Model : VOLKSWAGEN GOLF A7 1.2 TSI AT 5G12DZ

Chassis/Eng# : WVVZZZAUZFW332057/CJZ615695

REAR FENDER INNER TRIM CLIPS L/R - SET	2	50.00	+	100.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	50.00	30	50.00
REAR TAILGATE WINDSCREEN SEALANT	1	80.00	60	80.00
REAR TAILLAMP CLIPS L/R - SET	2	20.00	+	40.00
Subtotal before discount				810.00
Percentage discount 0%				0.00
Sub-total 2				810.00
Parts-total				30,443.97

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total	4,290.00
Parts & Labour Total	34,733.97

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is a computer-generated document which requires no signature.

page 4

Abm L Total: 15506.54
1/5 17/09/24 H/s: GK ✓
09 Days (Nett Value)