



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repair,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BLIKIT MERAH LANE 3, 401-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, 401-82, SINGAPORE 159723
TEL: 6271 7054, 6273 3304 FAX: 6273 8676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 25151300M GST Reg. No. M90367863L

SOMPO INSURANCE (S) PTE LTD
ATTN: THE MOTOR CLAIMS DEPT

ESTIMATE

CLAIM TYPE 3RD PARTY - SUPP 1
DATE OF ACCIDENT 27/08/2024
DATE 06/09/2024

VEHICLE NO.	MAKE/MODEL	CHASSIS NO.
SJJ7207D	BMW 216D ACTIVE TOURER D/AB LED	WBA2B32080V925787 (2017)

SN	DESCRIPTION	QTY	RATE	TAX	AMOUNT
1	Rear Boot <i>new ✓</i>	1	2,950.00	SR 9%	2,950.00
2	Rear Boot logo <i>new ✓</i>	1	196.00	SR 9%	196.00
3	Rear Boot Inner Lock <i>new ✓</i>	1	440.00	SR 9%	440.00
4	Rear Bumper <i>new ✓</i>	1	2,070.00	SR 9%	2,070.00
5	Rear Bumper Cover <i>new ✓</i>	1	260.00	SR 9%	260.00
6	Rear Bumper Parking Sensor LHS <i>cut ✓</i>	1	295.00	SR 9%	295.00
7	Rear Bumper Parking Sensor RHS <i>cut ✓</i>	1	295.00	SR 9%	295.00
8	Rear Bumper Parking Sensor Ring LHS <i>new ✓</i>	1	25.00	SR 9%	25.00
9	Rear Bumper Parking Sensor Ring RHS <i>new ✓</i>	1	25.00	SR 9%	25.00
10	Exhaust Silencer <i>X repair</i>	1	2,930.00	SR 9%	2,930.00
11					Subtotal: 9,486.00
12	Discount 10%	1	-948.60	SR 9%	-948.60
13	Sealant - S/NETT <i>new ✓</i>	1	35.00	SR 9%	35.00
14	Labour to remove and reinstall rear windscreen.	1	120.00 ✓	SR 9%	120.00
15	Check wiring function	1	40.00 ✓	SR 9%	40.00

16	Apply Rust Proofing	40 1	180.00	SR 9%	180.00
17	Remove and refit exhaust silencer.	80 1	180.00	SR 9%	180.00
18	Remove necessary parts. Jacking, panel beating, repair and straighten rear inner panel, rear end panel inclusive replacing the above.	500 1	900.00	SR 9%	900.00
19	Putty and respray rear inner panel, rear boot, rear end panel and rear bumper	500 1	900.00	SR 9%	900.00

Note: The above is an estimate only. If other parts requested during the course of repair, we will inform you accordingly. All parts are subject to availability.

SUBTOTAL	10,892.40
GST	980.32
TOTAL	S\$11,872.72

This is computer generated. No Signature is required.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



CHUAN'S AUTOCRAFT

Accident Claim Repair, Caravan, Building, Boat, Door Repair,
Spray-Painting, Mechanical Repair And Commissioning of Cars
BLOCK 1010, BUKIT MERAH LANE 3, 401-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, 401-02, SINGAPORE 159723
TEL: 6271 7054, 6273 3304 FAX: 6273 8676 EMAIL: chuan@singnet.com.sg
Bus. Reg. No. 25151300M GST Reg. No. M90367883L

SOMPO INSURANCE (S) PTE LTD
ATTN: THE MOTOR CLAIMS DEPT

ESTIMATE

CLAIM TYPE 3RD PARTY - SUPP 1
DATE OF ACCIDENT 27/08/2024
DATE 14/11/2024

VEHICLE NO.	MAKE/MODEL	CHASSIS NO.
SJJ7207D	BMW 216D ACTIVE TOURER D/AB LED	WBA2B32080V925787 (2017)

SN	DESCRIPTION	QTY	RATE	TAX	AMOUNT
1	Rear Boot Sensor Support <i>cm</i>	1	120.00	SR 9%	120.00
2	Rear Bumper Bracket/Guide LHS <i>cm</i>	1	210.00	SR 9%	210.00
3	Rear Bumper Bracket/Guide RHS <i>cm</i>	1	210.00	SR 9%	210.00
4					Subtotal: 540.00
5	Discount 10%	1	-54.00	SR 9%	-54.00

Note: The above is an estimate only. If other parts requested during the course of repair, we will inform you accordingly. All parts are subject to availability.

SUBTOTAL 486.00
GST 43.74
TOTAL \$529.74

This is computer generated. No Signature is required.

Parts - 6296

Supp - 540

- 10% 683.60

S/N - 35

LAB - 1280

less 20% - 5973.92