



SOMPO INSURANCE (S) PTE LTD
ATTN: THE MOTOR CLAIMS DEPT

ESTIMATE

CLAIM TYPE 3RD PARTY - SUPP 1
DATE OF ACCIDENT 27/08/2024
DATE 06/09/2024

VEHICLE NO.	MAKE/MODEL	CHASSIS NO.
SJJ7207D	BMW 216D ACTIVE TOURER D/AB LED	WBA2B32080V925787 (2017)

SN	DESCRIPTION	QTY	RATE	TAX	AMOUNT
1	Rear Boot	1	2,950.00	SR 9%	2,950.00
2	Rear Boot logo	1	196.00	SR 9%	196.00
3	Rear Boot Inner Lock	1	440.00	SR 9%	440.00
4	Rear Bumper	1	2,070.00	SR 9%	2,070.00
5	Rear Bumper Cover	1	260.00	SR 9%	260.00
6	Rear Bumper Parking Sensor LHS	1	295.00	SR 9%	295.00
7	Rear Bumper Parking Sensor RHS	1	295.00	SR 9%	295.00
8	Rear Bumper Parking Sensor Ring LHS	1	25.00	SR 9%	25.00
9	Rear Bumper Parking Sensor Ring RHS	1	25.00	SR 9%	25.00
10	Exhaust Silencer	1	2,930.00	SR 9%	2,930.00
11					Subtotal: 9,486.00
12	Discount 10%	1	-948.60	SR 9%	-948.60
13	Sealant - S/NETT	1	35.00	SR 9%	35.00
14	Labour to remove and reinstall rear windscreen.	1	120.00	SR 9%	120.00
15	Check wiring function	1	40.00	SR 9%	40.00

16	Apply Rust Proofing	1	180.00	SR 9%	180.00
17	Remove and refit exhaust silencer.	1	180.00	SR 9%	180.00
18	Remove necessary parts. Jacking, panel beating, repair and straighten rear inner panel, rear end panel inclusive replacing the above.	1	900.00	SR 9%	900.00
19	Putty and respray rear inner panel, rear boot, rear end panel and rear bumper	1	900.00	SR 9%	900.00

Note: The above is an estimate only. If other parts requested during the course of repair, we will inform you accordingly. All parts are subject to availability.

SUBTOTAL	10,892.40
GST	980.32
TOTAL	S\$11,872.72

This is computer generated. No Signature is required.