



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24090293/Rqp3e2
(BUDGET DIRECT INSURANCE)	Date:	11/10/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNB 578Z	Veh. Inspected	SLT 2216J
Policy No.	P10769827R02	Coverage	0
Claim No.	C10031679/MC	Excess	\$0.00
Assign From	MONIXCA CHUNG	Assign Date	17/09/2024

### 2. Vehicle Details

Make & Model	TOYOTA HARRIER G GRADE	C.C	1998
Engine No.	8ARZ093956	Year of Reg.	23/10/2017
Chassis No.	JTEKB3GH10J000482	Colour	BLACK
Odometer	97121 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/55 R18	MICHELIN	6
L/H Front Tyre	235/55 R18	MICHELIN	6
R/H Rear Tyre	235/55 R18	MICHELIN	6
L/H Rear Tyre	235/55 R18	MICHELIN	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	13/09/2024	Inspection Date	25/09/2024
Survey held at	5 SOON LEE STREET #03-14, PIONEER POINT SINGAPORE 627607 - REPAIRER: COMPLETE VMS PTE LTD		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days