

WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com

Mobile : +65 9009 6622

Not Authorized

mean

18/9/24

3 days 2/5 & 4000

17 September 2024

REG NO. : SLG9001J
MAKE/MODEL : HONDA VEZEL

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Front RH Headlamp	1759.20 with \$ cr 2,418.82
1	Front Bumper	801.00 cur \$ 1,126.84
1	Front Bumper Inner Sponge	\$ 11 241.10 X
1	Front Bumper Reinforcement	\$ 11 698.20 X
1	Front Bumper Lower Lid	\$ 11 588.80 X
1	Front Bumper Side Retainer	\$ 56 128.00 X
1	Front RH Fender	\$ 568.00 X
1	Front RH Fender Inner Shield	266.80 \$ 368.60
1	Front RH Fender Wheel Arch Garnish	280.40 \$ 369.50
1	Front RH Wheel Rim	\$ 1,260.00 480 S/N
1	Front Wheel Hub With Bearing	488.20 \$ 585.80
1	Front Shock Absorber	\$ 518.98 X
1	Front Knuckle Arm	366.80 \$ 608.26
1	Front Lower Arm	390.60 \$ 628.00
		\$ 10,108.90
	Less 20%	\$ 2,021.78
		\$ 8,087.12
<u>SPECIAL NETT ITEMS</u>		
1	Front Tyre	\$ 11 450.00 X
1	Front Fender Inner Shield Clip (1 Set)	\$ 80.00 30 S/N
1	Front Bumper Clip (1 Set)	\$ 90.00 30 S/N
		\$ 620.00
<u>LABOUR CHARGES</u>		
1	To Check Wiring, Lighting And Resetting Headlamps Focusing	\$ 80.00 20
2	To Remove And Refit Front Undercarriage.	\$ 350.00 120
3	To Conduct Wheel Alignment	\$ 180.00 60
4	To Apply Undercoating.	\$ 11 180.00 X
5	Panel Beating.	\$ 1,500.00 380
6	To Re-spray Painting On The Affected Areas.	\$ 1,400.00 400
		\$ 3,690.00

\$ 12,397.12

LKK Auto Consultants hence notify the Repairer of the following:

- To spray painting
- To display damaged parts for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Page 1 of 1

Signature:

Date:

1-4383
20
3482.40
540
980
5002.4