

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24090296/UUA3Q2
Date: 09/12/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0004186_02
Claimant Vehicle No : SKR6587J Insured Vehicle No : SNM2096B
Date of Loss: 13/09/2024 Nature of Claim: TP Claim No: MFL2024D0010838

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKR6587J
Make & Model: AUDI A3, 1.4 TFSI (A) Engine No: CHZC32580
Reg. Date: 11/12/2020 (Man. Year: 2019) Chassis No: WAUZZZ8V0KA117881
Colour: White Odometer: 99628 km
Engine Capacity: 999 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,783.70	7,139.70	1,644.00	18.72
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	2,880.00	1,380.00	1,500.00	52.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,675.70	8,531.70	3,144.00	26.93
Approved Total (Overridden) (S\$)		6,800.00		
(S\$)	11,675.70	6,800.00	4,875.70	41.76
+ GST 9.00/9.00% (S\$)	1,050.81	612.00	438.81	41.76
Nett Amount (S\$)	12,726.51	7,412.00	5,314.51	41.76
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
Nett Liability (S\$)		7,652.00		
Global Sum Settlement (S\$)		7,650.00		

INSPECTION

Date of Assignment: 17/09/2024 Present Location: NPH Auto Service (HQ)
Date Inspected: 17/09/2024 Inspected At: NPH Auto Service (HQ)
Estimated Period of Repair: 4.0 days Blk 9005 Tampines Steet 93, #01-246/254
Singapore 528839

Adjuster: MARCUS CHUA

Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Oct 2024)
Parts:	143	AUDI A3 1.4 TFSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR6587J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Dented / Bent	3,307.00 FL	*3,163.00 FL
2	1		*FRONT DOOR OUTER HANDLE	Cut	416.00 FL	*416.00 FL
3	1		*FRONT DOOR OUTER HANDLE JOINT	Serviceable	88.00 FL	*- FL
4	1		*FRONT DOOR OUTER TOP MOULDING	Necessary	351.00 FL	*351.00 FL
5	1		*FRONT DOOR W/STRIP RUBBER	Necessary	182.00 FL	*182.00 FL
6	1		*FRONT DOOR INNER LOCK	Not Necessary	673.00 FL	*- FL
7	1		*FRONT DOOR INNER LOCK CATCH	Not Necessary	88.00 FL	*- FL
8	1		*FRONT DOOR INNER SOUND PROOF PLASTIC	Not Necessary	85.00 FL	*- FL
9	1		*REAR DOOR RH	Dented / Bent	3,307.00 FL	*3,307.00 FL
10	1		*REAR DOOR HINGE TOP	Not Necessary	65.00 FL	*- FL
11	1		*REAR DOOR HINGE BOTTOM	Not Necessary	85.00 FL	*- FL
12	1		*REAR DOOR GLASS OUTER CHROME MOULDING	Necessary	332.00 FL	*332.00 FL
13	1		*REAR DOOR W/STRIP RUBBER	Necessary	182.00 FL	*182.00 FL
14	1		*REAR DOOR SOUND PROOF PLASTIC	Not Necessary	85.00 FL	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	9,246.00 7,933.00
					- List Item Discount on L Items 5.00/10.00% (\$\$)	462.30 793.30
					Total Parts (\$\$)	8,783.70 7,139.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & INSTALL F/REAR DOOR ASSY, KNOCK RUNNING BOARD PANEL, DOOR CENTER PILLAR AND RESTRAIGHTHEN BODY.	New	1,200.00	500.00
2	SPRAY PAINTING.	New	1,300.00	800.00
3	REMOVE & INSTALL SEAT, CARPET AND SEAT BELT.	New	180.00	0.00
4	RESET ECU.	New	200.00	80.00
Gross Labour Cost (\$\$)			2,880.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >