

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
	<u>LABOUR</u>						
1	TO REMOVE & REPLACE REAR BUMPER, BOOT LID, END PANEL, FRONT BUMPER, BONNET, FRONT PANEL, HEADLAMP FRONT & ALL ACCIDENT DAMAGE BODY PARTS & ALL AREAS AFFECTED BY THE ACCIDENT	1		\$1,800.00	\$ 1,800.00	1000	\$ 1,800.00
2	TO SPRAY BUMPER REAR, BOOT LID, END PANEL, BUMPER REINFORCEMENT REAR, BUMPER FRONT, BONNET, BUMPER REINFORCEMENT FRONT, BOOT FLOOR REAR	1		\$1,800.00	\$ 1,800.00	1000	\$ 1,800.00
3	TO REPAIR BOOT FLOOR REAR	1		\$200.00	\$ 200.00	17X	\$ 200.00
4	TO REPLACE/TRANSFER THE REAR BUMPER SENSORS & OTHER PARTS	1		\$200.00	\$ 200.00	30	\$ 200.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	1		\$150.00	\$ 150.00	30	\$ 150.00
6	TO PROGRAMME AFTER THE ACCIDENT REPAIR WORKS	1		\$200.00	\$ 200.00	50	\$ 200.00
7	TO CARRY OUT BODY CAVITY PRESERVATION	1		\$200.00	\$ 200.00	17X	\$ 200.00
8	SUNDRIES	1		\$100.00	\$ 100.00	17X	\$ 100.00
	<u>PARTS</u>						
1	BUMPER REAR	1		\$1,865.25	\$ 1,865.25	0.5	\$ 1,865.25
2	BUMPER CLIPS (SET)	1	1set	\$135.55	\$ 135.55	121	\$ 135.55
3	BOOT LID	1		\$2,864.35	\$ 2,864.35	2	\$ 2,864.35
4	EXHAUST SILENCER REAR	1		\$2,252.40	\$ 2,252.40	2	\$ 2,252.40
5	BUMPER REAR LOWER SKIRTING	1		\$209.30	\$ 209.30	0.5	\$ 209.30
6	TOW EYE COVER REAR RH	1		\$37.55	\$ 37.55	17	\$ 37.55
7	SENSOR REAR RH (INNER)	1		\$194.75	\$ 194.75	malhutan	\$ 194.75
8	END PANEL ASSY REAR	1	860	\$1,331.65	\$ 1,331.65	1.5-2.5	\$ 1,331.65
9	END PANEL INNER TRIM	1		\$161.45	\$ 161.45	NF	\$ 161.45
10	BUMPER REINFORCEMENT REAR	1		\$458.65	\$ 458.65	50	\$ 458.65
11	BOOT LID LOCK	1		\$159.35	\$ 159.35	50	\$ 159.35
12	BOOT LID BADGE [A4]	1		\$72.30	\$ 72.30	21	\$ 72.30
13	BOOT LID BADGE [TFSI]	1		\$72.30	\$ 72.30	21	\$ 72.30
14	BOOT LID BADGE [LOGO]	1		\$93.65	\$ 93.65	100	\$ 93.65

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
15	BUMPER FRONT	1		\$1,794.25	\$ 1,794.25	20/a	\$ 1,794.25
16	GRILLE FRONT	1		\$829.60	\$ 829.60	320	\$ 829.60
17	NUMBER PLATE FRONT	1		\$30.00	\$ 30.00	3ent	\$ 30.00
18	BUMPER SHOCK ABSORBER FRONT	1		\$89.20	\$ 89.20	7000	\$ 89.20
19	GRILLE BADGE [LOGO]	1		\$93.65	\$ 93.65	c/w s/n/e	\$ 93.65
20	BONNET	1		\$2,025.75	\$ 2,025.75	12	\$ 2,025.75
21	BONNET HINGE LH	1		\$54.70	\$ 54.70	17	\$ 54.70
22	BONNET HINGE RH	1		\$54.70	\$ 54.70	17	\$ 54.70
23	BONNET INSULATION	1		\$246.90	\$ 246.90	17	\$ 246.90
24	BONNET INSULATION CLIPS	10		\$3.50	\$ 35.00	17	\$ 35.00
25	AIRCOND CONDENSER	1		\$813.45	\$ 813.45	su	\$ 813.45
26	RADIATOR	1		\$728.25	\$ 728.25	21	\$ 728.25
27	BUMPER REINFORCEMENT FRONT	1		\$677.70	\$ 677.70	321	\$ 677.70
28	FRONT PANEL [SUPPORT PANEL]	1		\$800.75	\$ 800.75	su	\$ 800.75
29	HEADLAMP ASSY FRONT LH	1		\$1,861.05	\$ 1,861.05	su	\$ 1,861.05
30	HEADLAMP ASSY FRONT RH	1		\$1,861.05	\$ 1,861.05	cm	\$ 1,861.05
31	RADIATOR AIR DEFLECTOR LH	1		\$75.90	\$ 75.90	17	\$ 75.90
32	RADIATOR AIR DEFLECTOR RH	1		\$75.90	\$ 75.90	17	\$ 75.90
33	TOW EYE COVER FRONT RH	1		\$46.70	\$ 46.70	17	\$ 46.70
34	GRILLE FRONT UPPER COVER	1		\$91.35	\$ 91.35	17	\$ 91.35
35	BUMPER FRONT SIDE RETAINER LH	1		\$35.55	\$ 35.55	17	\$ 35.55
36	BUMPER FRONT SIDE RETAINER RH	1		\$35.55	\$ 35.55	17	\$ 35.55
37	BUMPER REAR SIDE RETAINER LH	1		\$38.85	\$ 38.85	17	\$ 38.85
38	BUMPER REAR SIDE RETAINER RH	1		\$38.85	\$ 38.85	17	\$ 38.85
39	AIRCOND GAS	1		\$60.00	\$ 60.00	17	\$ 60.00
40	RADIATOR COOLANT	1		\$40.00	\$ 40.00	17	\$ 40.00
41	WINDSCREEN SEALANT	1		\$80.00	\$ 80.00	17	\$ 80.00
42	FLOOR BOARD SEALANT	1		\$80.00	\$ 80.00	17	\$ 80.00
				SUBTOTAL	\$ 27,253.15	SUBTOTAL	\$ 27,253.15
				GST 9%	\$ 2,452.78	GST 9%	\$ 2,452.78
				TOTAL	\$ 29,705.93	TOTAL	\$ 29,705.93

REMARKS:

for support panel top garnish

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD

headbury inner bracket RH

one x 147



(CUSTOMER'S SIGNATURE AND COMPANY STAMP)

Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(AUTHORISED SIGNATURE)

P-8913-7

102

802233

40

2110

1017233

203

A337