

ASS. REC. BY:

REF: TH /Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s JDof 746N

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$22k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBE3395R Yr Regn: 11.15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Hiace C.G. 2982Colour: White A/C: Insured / Std / NI / NASp. Reading: 210910 T/Radio: Insured / Std / NI / NA

EngNo: _____

C/No: KD14 201 0154203

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII S/Rim / STD A/Rim orTyre Size: Falken 195R15X8R: Dun

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 4 mmL/Bal. 4 mmD.O.A. 13/6/24

Survey held at

Rear

R/Bal. 3 mmL/Bal. 3 mmD.O.I. 21/6/2024Des. of Damages: Frt / Rear O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>Will send GIA over.</u>

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ _____)



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD # 05-76 SYNERGY @ KB S417800

DATE : 20/6/2024
VEHICLE : GBE339SR
MAKE/MODEL : TOYOTA HIACE
CHASSIS NO : KDH2010154203
MILLAGE :
TYRE SIZE :
DOA : 13/6/2024

Not Authorize
L/Rp &
Penny After Pain
5 days

List items

01 PC	TAILGATE
01 PC	TAILGATE INNER LOCK
01 PC	TAILGATE INNER LOCK COVER
01 PC	TAILGATE CATCH LOCK
01 PC	TAILGATE INNER TRIM BOARD
01 PC	TAILGATE WEATHERSTRIP
02 PC	TAILGATE DAMPER @\$301.70
01 PC	TAILGATE OUTER HANDLE
02 PC	TAILGATE STOPPER SET @\$160.30
01 PC	TAILGATE OUTER GANISH
01 PC	TAILGATE KEY SWITCH
01 PC	TAILGATE EMBLEM 'LOGO'
02 PC	TAIL LAMP @\$380.30
01 PC	REAR BUMPER
02 PC	REAR BUMPER SIDE RETAINER @\$98.90
02 PC	REAR CORNER PANEL @\$165.20
02 PC	REAR TOWING COVER @\$65.30
01 PC	REAR END PANEL
01 PC	REAR INNER STEP GANISH
01 PC	REAR FLOOR PANEL
01 PC	REAR FLOOR CARPET
01 PC	REAR UNDER SPARE TYRES BRACKET
01 PC	REAR UNDER SPARE TYRES BRACKET HOOK

Ry S	1,685.40	✓
Trms	328.70	✓
S	85.60	7
S	130.20	7
Rm S	258.60	X
S	256.01	7
Rm S	603.40	X
Rm S	120.80	X
Ins	320.60	X
Rm S	430.20	X
S	156.70	7
Rms	180.30	✓
N/S km	760.60	LT
R/L CM S	673.50	✓
N/S DITS	197.80	LT
Rm	330.40	X
N/S P	130.60	X
Ry S	896.40	✓
S	319.80	7
REPAIR		
Rm S	649.50	X
S	656.40	7
S	147.60	7
<u>\$ 9,319.11</u>		

TOTAL PARTS COST

Special Nett Item:

12 PC	TAILGATE TRIM BOARD CLIP @\$6
06 PC	REAR BUMPER CLIP @\$6
02 PC	PARKING SENSOR @\$280
01 PC	REAR WINDSCREEN SEALANT
01 PC	HIACE STICKER
01 PC	70KM STICKER
01 PC	1250KG STICKER
02 PC	BUMPER REFLECTOR STICKER @\$30

NNS	72.00	X
Rm S	36.00	✓
CM S	560.00	200IN
Rm S	60.00	405m
Rm S	60.00	✓
Rm S	30.00	15IN
Rm S	30.00	✓
Rm S	60.00	20IN
<u>\$ 908.00</u>		

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA
3. TO SUPPLY LABOUR FOR REMOVE AND REFIT REAR WINDSCREEN
5. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL
6. TO SUPPLY LABOUR TO REWIRE REPLACEMENT

\$	1,800.00	6001
\$	600.00	4501
\$	250.00	1201
\$	250.00	801
\$	100.00	201
<u>\$ 3,000.00</u>		

TOTAL PARTS
SPECIAL NETT ITEM
TOTAL LABOUR
TOTAL COST OF REPAIR

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$	9,319.11
\$	908.00
\$	3,000.00
<u>\$ 13,227.11</u>	