



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 20/6/2024
VEHICLE : GBE3395R
MAKE/MODEL : TOYOTA HIACE
CHASSIS NO : KDH2010154203
MILLAGE :
TYRE SIZE :
DOA : 13/6/2024

Not Authorised
11 Rpm @ 4000h
Penny After Paint
5 days

List items

01 PC	TAILGATE
01 PC	TAILGATE INNER LOCK
01 PC	TAILGATE INNER LOCK COVER
01 PC	TAILGATE CATCH LOCK
01 PC	TAILGATE INNER TRIM BOARD
01 PC	TAILGATE WEATHERSTRIP
02 PC	TAILGATE DAMPER @ \$301.70
01 PC	TAILGATE OUTER HANDLE
02 PC	TAILGATE STOPER SET @ \$160.30
01 PC	TAILGATE OUTER GANISH
01 PC	TAILGATE KEY SWITCH
01 PC	TAILGATE EMBLEM 'LOGO' 75.30
02 PC	TAIL LAMP @ \$380.30
01 PC	REAR BUMPER
02 PC	REAR BUMPER SIDE RETAINER @ \$98.90
02 PC	REAR CORNER PANEL @ \$165.20
02 PC	REAR TOWING COVER @ \$65.30
01 PC	REAR END PANEL 708.10
01 PC	REAR INNER STEP GANISH
01 PC	REAR FLOOR PANEL
01 PC	REAR FLOOR CARPET
01 PC	REAR UNDER SPARE TYRES BRACKET 388.10
01 PC	REAR UNDER SPARE TYRES BRACKET HOOK

TOTAL PARTS COST

251

By \$	1,685.40	✓
Tr \$	328.70	✓
Sh \$	85.60	✓
Di \$	130.20	✓
Pr \$	258.60	✓
Sw \$	256.01	✓
Pr \$	603.40	✓
Pr \$	120.80	✓
Pr \$	320.60	✓
Pr \$	430.20	✓
Pr \$	156.70	✓
Pr \$	180.30	✓
N/S Wt \$	760.60	✓
AT/CMA \$	673.50	✓
N/S Di \$	197.80	✓
Pr \$	330.40	✓
N/S \$	130.60	✓
Pr \$	896.40	✓
Sw \$	319.80	✓
REPAIR		
Pr \$	649.50	✓
Pr \$	656.40	✓
Pr \$	147.60	✓

\$ 9,319.11

Special Nett Item:

12 PC	TAILGATE TRIM BOARD CLIP @ \$6
06 PC	REAR BUMPER CLIP @ \$6
02 PC	PARKING SENSOR @ \$280
01 PC	REAR WINDSCREEN SEALANT
01 PC	HIACE' STICKER
01 PC	70KM' STICKER
01 PC	1250KG' STICKER
02 PC	BUMPER REFLECTOR STICKER @ \$30

NA \$	72.00	✓
NA \$	36.00	✓
NA \$	560.00	2005N
NA \$	60.00	405N
NA \$	60.00	✓
NA \$	30.00	151N
NA \$	30.00	✓
NA \$	60.00	201N
\$ 908.00		

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA
3. TO SUPPLY LABOUR FOR REMOVE AND REFIT REAR WINDSCREEN
5. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL
6. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS

\$	1,800.00	6001
\$	600.00	4501
\$	250.00	1201
\$	250.00	801
\$	100.00	201
\$ 3,000.00		

TOTAL PARTS
SPECIAL NETT ITEM
TOTAL LABOUR
TOTAL COST OF REPAIR

\$	9,319.11
\$	908.00
\$	3,000.00
\$ 13,227.11	

JKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: