

Date: 17/09/2024

Vehicle No: SNB9255X

Model: SUZUKI SWIFT SPORT 1.4 6MT

Chassis: K14D1161049-2021

Reg. Year: 2021

Third Party Insurer: AIG

Third Party Veh No: SGC1121D

Date of Accident: 15/09/2024

Estimator: TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAIL LAMP RH <i>820.60</i>	1		<i>cm</i> \$880.00 ✓
2	REAR BUMPER <i>1086.50</i>	1		<i>cm</i> \$1,333.00 ✓
3	REAR BUMPER SIDE BRACKET	1		<i>cm</i> \$35.00 ✓
SUB TOTAL				\$2,248.00
LESS 15%				-\$337.20
PARTS TOTAL				\$1,910.80 ✓

Finalise.
Parts: \$1910.80
Nett: \$50
Labour: \$470
PTP: \$2430.80

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		<i>na</i> \$50.00 ✓
2	REAR BUMPER REVERSE SENSOR	1		<i>na</i> \$300.00 X
S/N TOTAL				\$350.00 \$50

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$300.00 *200*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER & ETC.

\$250.00 *200*

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$120.00 *50*

TO DAIGNOSIS FAULT CODE & ETC.

na \$120.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$120.00 *20*

LABOUR TOTAL \$910.00 \$470

TING AN

TOTAL

\$3,170.80

Head Office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 6 Singapore 554500
Tel: (+65) 6484 9910 | Fax: (+65) 6481 1893

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

