

Date: 17/09/2024

Vehicle No: SNB9255X

Model: SUZUKI SWIFT SPORT 1.4 6MT

Chassis: K14D1161049-2021

Reg.Year: 2021

Third Party Insurer: AIG

Third Party Veh No: SGC1121D

Date of Accident: 15/09/2024

Estimator: TING AN

Surveyor:

*Not Authorised
Resurvey B4 paint
2 day*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAIL LAMP RH	1		<i>CM</i> \$880.00 ✓
2	REAR BUMPER	1		\$1,333.00 ?
3	REAR BUMPER SIDE BRACKET	1		\$35.00 ?
SUB TOTAL				\$2,248.00
LESS 15%				-\$337.20
PARTS TOTAL				\$1,910.80

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		<i>na</i> \$50.00 ✓
2	REAR BUMPER REVERSE SENSOR	1		<i>na</i> \$300.00 X
S/N TOTAL				\$350.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

200 \$300.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER & ETC.

200 \$250.00

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

50 \$120.00

TO DAIGNOSIS FAULT CODE & ETC.

na \$120.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM.

200 \$120.00

LABOUR TOTAL \$910.00

TING AN

TOTAL \$3,170.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____ Date: _____

Head office

6 Kung Chong Road Singapore 159061
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2712

Branch

9A Serangoon North Ave 5 Singapore 554509
Tel: (+65) 6481 9919 | Fax: (+65) 6481 1893

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

