



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 47693

INDIA INTERNATIONAL INSURANCE P.L.

64 CECIL STREET

#04-00 & #06-00

IOB BUILDING

SINGAPORE 049711

ATTN: INDIA INTERNATIONAL INSURANCE P.L.

DATE : 17/09/2024

CLAIM NO. : 12593

POLICY NO. : P20709776R00

FROM : STEPHANIE

VEHICLE NO. : FBS13P

MAKE/MODEL : BMW / S1000XR

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE (BLACK) / BT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$744.00	744.00 /
2	BEARING ? / Nec P/N: 78515 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$101.00	202.00 /
3	BRACKET COVER LOWER FRONT RH / APC - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00 /
4	BRACKET UNDER FORK ? / BT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,271.00	1,271.00 /
5	BRAKE EXTENDER (WUNDERLICH) / BR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$403.00	403.00 /
6	CAMERA SET / cut / shadow - (REPORTED BY MECHANIC)	REPLACE	1.00	\$558.00	558.00 /
7	COVER FRONT LOWER RH - (REPORTED BY MECHANIC) / cut	REPLACE	1.00	\$186.00	186.00 /
8	ENGINE SLIDER / cut - (REPORTED BY MECHANIC)	REPLACE	1.00	\$512.00	512.00 /
9	FOOTREST FRONT RH / BT P/N: 67772 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$264.00	264.00 /



bizSAFE₃



Blk 8 Defu South Street 1, #04-28, JTC Defu Industrial City, Singapore 533758 | Tel: +65 6281 6520 | www.bhh.com.sg
Fax: (Main) + 65 6281 2830, (Spare Parts) + 65 6285 7530, (Insurance/Project) + 65 6284 2969, (Accounts) + 65 6281 6759

CERT NO.: 2003 1-0383
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
10	FORK FRONT ASSY LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$4,495.00	4,495.00 /
11	FORK FRONT ASSY RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$4,495.00	4,495.00 /
12	HANDGUARD PROTECTOR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$752.00	752.00 /
13	KIT MAIN STAND P/N: 67771 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$140.00	140.00
14	LABOUR P/N: 06766 (Labour) - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	Supply/Install	16.00	\$85.00 55	1,360.00 880 / Labour
15	MIRROR RH (MOTOGADGET) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$574.00	574.00 /
16	MUFFLER (LEO VINCE) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,938.00	1,938.00 /
17	PEDAL BRAKE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$434.00	434.00 /
18	PROTECTOR HANDGUARD CARBON - (REPORTED BY MECHANIC)	REPLACE	1.00	\$899.00	899.00 /
19	RUBBER FOOTREST P/N: 67770 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$46.00	46.00 /
20	SEAL DUST - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	34.00 /
21	SIGNAL LAMP FRONT LH RH P/N: 55766 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$170.00	170.00 /
22	TAIL LAMP - (REPORTED BY MECHANIC)	REPLACE	1.00	\$294.00	294.00 /
23	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2 P/N: 45836		1.00	\$85.00	85.00 / nett

Stew (LKK)
18/9/24, 12.00
w ll

SUB TOTAL
GST @ 9 %

GRAND TOTAL (SGD)

\$19,884.00
\$1,789.56

\$21,673.56

50% deposit required before ordering o



P/P

My Ref. sy
3 days

Blk 8 Defu South Street 1, #04-28, JTC Defu Industri
Fax: (Main) + 65 6281 2830, (Spare Parts) + 65 6285

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

18,299.00

-10%

16,469.10 + 960 (labour/nett)

= 17,429.10

bizSAFE₃



h.com.sg
65 6281 6759

CERT NO: 2003 1-0343
ISS 08/11/2015