

YEW TEE AUTOMOBILE TECH PTE LTD

39 WOODLANDS CLOSE #01-12 MEGA@WOODLANDS S(737856)
25 KAKI BUKIT ROAD 4 #01-61 SYNERGY@KB S(417800)

To: INDIA INSURANCE

DATE: 12.09.2024

Dear Sir / Madam:

RE: VEHICLE REPAIR ESTIMATE

Owner : MOHAMAD PAUZI BIN KASSIM

Model : YAMAHA T150

Reg : FBS8292Y Chassis : MH3UG131000002072 DOAccident : 26.08.2024

THIRD PARTY CLAIM AGAINST

We are please to submit our estimate of repairs to the above mention vehicle.

		Parts	Labour
1	FRONT FORK (SET)	\$ 669.00	bt
2	FRONT FENDER	\$ 170.00	as
3	FRONT FENDER INNER SHIELD	\$ 220.00	dis
4	FRONT FAIRING	\$ 350.00	dis
5	FRONT FAIRING CENTRE	\$ 280.00	dis
6	FRONT FAIRING LAMP	\$ 480.00	cur
7	FRONT FAIRING INNER FAIRING	\$ 380.00	de
8	FRONT HEADLAMP	\$ 470.00	cut
9	FRONT HEADLAMP FAIRING	\$ 310.00	cut
10	FRONT HEADLAMP LOWER FAIRING	\$ 330.00	mig
11	FRONT SIDE MIRROR LH	\$ 85.00	cut
12	FRONT SIDE MIRROR RH	\$ 85.00	bno
13	FRONT HANDLE BAR	\$ 270.00	?
14	FRONT HANDLE BAR GRIP RH	\$ 65.00	cut
15	FRONT BRAKE LEVER RH	\$ 45.00	cut
16	FRONT CLUTCH LEVER LH	\$ 45.00	cut
17	FRONTT STEERING CONE	\$ 165.00	bt
18	CHASSIS FRAME		REPAIR
19	ENGINE COVER RH	\$ 420.00	cur
20	FRONT SIDE FAIRING LH	\$ 360.00	dis
21	FRONT SIDE FAIRING RH	\$ 360.00	mig
22	RADIATOR	\$ 600.00	bt
23	CENTRE FAIRING LH	\$ 280.00	de
24	CENTRE FAIRING RH	\$ 280.00	de
25	REAR FAIRING RH	\$ 330.00	cut
26	FRONT FOOT BRAKE RH	\$ 220.00	bt
27	FRONT FOOT REST RH	\$ 45.00	dd
28	FRONT FOOT REST BRACKET RH	\$ 165.00	bt
29	REAR EXHAUST PIPE	\$ 1,180.00	bt
30	REAR EXHAUST PIPE OUTER COVER RH	\$ 210.00	cut
31	REAR EXHAUST PIPE OUTER TAILCOVER RH	\$ 170.00	cut
32	REAR FOOT REST RH	\$ 45.00	bno
33	REAR FOOT REST BRACKET RH	\$ 165.00	XR
Total Parts :		\$ 9,249.00	
Less	10%	\$ 924.90	
		\$ 8,324.10	

YEW TEE AUTOMOBILE TECH PTE LTD

39 WOODLANDS CLOSE #01-12 MEGA@WOODLANDS S(737856)

25 KAKI BUKIT ROAD 4 #01-61 SYNERGY@KB S(417800)

34	FRONT NUMBER PLATE	nett	\$	35.00	20 b1-
35	FRONT WHEEL RIM	nett	\$	250.00	bt-
36	FRONT TYRE	nett	\$	250.00	put new - 80%
37	ENGINE COVER GASKET RH	nett	\$	70.00	new
38	ENGINE OIL	nett	\$	120.00	new 80
39	REAR NUMBER PLATE	nett	\$	35.00	b1-
40	ERP UNIT	nett	\$	190.00	dis
41	TO ELECTRICAL WIRING SERVICES		\$	40.00	30
42	TO DISMANTLE & REFIT FRONT UNDERCARRIAGE		\$	150.00	x
43	TO COMPUTER WHEEL BALANCING		\$	60.00	x
44	To remove, refix, realign, adjust and replace all damaged parts.		\$	480.00	450
45	TO UNDERCOATING FOR RUST PROTECTION		\$	50.00	x
46	To respray paint of accident section.		\$	350.00	250
			\$	2,080.00	

Grand Total :

\$ 10,404.10

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

Shaun : 97432262

Tanji 97445749 / 62563561
 WP 18/9/24 @ 330pm
 * To check repair limit
 L/S Rosny after repair
 Tanji e Khawto-u
 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: