

Company Reg No: 202136905K

Tel : 6341 6789 Fax: 6341 6778
E-mail: ilperfectautowork@gmail.com



DATE : 12.09.2024

TO	:	AIG MOTOR CLAIMS DEPTS
VEHICLE NO	:	SLD6237G
MODEL	:	PEUGEOT 508
DATE OF ACCIDENT	:	06.09.2024
TIME OF ACCIDENT	:	14:30 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID <i>new</i>	1	\$ 1,347.00	\$ 1,347.00
2	BOOTLID LOWER GARNISH <i>could be</i>	1	\$ 587.00	\$ 587.00
3	BOOT LID LOGO	1	\$ 132.00	\$ 132.00
4	BOOT LID EMBLEM 'PEUGEOT' <i>new</i>	1	\$ 98.00	\$ 98.00
5	BOOT LID EMBLEM '508' <i>new</i>	1	\$ 88.00	\$ 88.00
6	BOOT LID TOP LOCK <i>new</i>	1	\$ 111.00	\$ 111.00
7	BOOT LID LOWER LOCK <i>new</i>	1	\$ 111.00	\$ 111.00
8	BOOT LID DETECTOR <i>new</i>	1	\$ 352.00	\$ 352.00
9	BOOT LID HINGE <i>new</i>	2	\$ 136.00	\$ 272.00
10	BOOT LID WEATHERSTRIP <i>cut</i>	1	\$ 277.00	\$ 277.00
11	REAR BUMPER <i>Rehnd</i>	1	\$ 1,065.00	\$ 1,065.00
12	REAR BUMPER LOWER (CENTER) <i>Rehnd</i>	1	\$ 252.00	\$ 252.00
13	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 477.00	\$ 477.00
14	REAR BUMPER SIDE REFLECTOR <i>new</i>	2	\$ 65.00	\$ 130.00
15	REAR BUMPER SIDE REFLECTOR CHROME <i>new</i>	2	\$ 85.00	\$ 170.00
16	REAR BUMPER NUMBER PLATE LAMP <i>new</i>	2	\$ 95.00	\$ 190.00
17	REAR BUMPER TOWING COVER <i>new</i>	1	\$ 76.00	\$ 76.00
18	REAR BUMPER ABSORB GARNISH <i>Rehnd</i>	1	\$ 228.00	\$ 228.00
19	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 115.00	\$ 230.00
20	TAIL LAMP <i>could be</i>	2	\$ 865.00	\$ 1,730.00
21	TAIL LAMP LOWER BRACKET <i>new</i>	2	\$ 96.00	\$ 192.00

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLD6237G**
 MODEL : **PEUGEOT 508**
 DATE OF ACCIDENT : 06.09.2024
 TIME OF ACCIDENT : 14:30 HOURS

22	REVERSE CAMERA <i>new</i>	1	\$ 1,358.00	\$ 1,358.00	<i>+</i>
23	REVERSE SENSOR <i>new</i>	2	\$ 492.00	\$ 984.00	<i>Sw</i>
24	REVERSE SENSOR HOLDER <i>new</i>	6	\$ 62.00	\$ 372.00	<i>+</i>
25	REAR FENDER INNER COWLING <i>new</i>	2	\$ 196.00	\$ 392.00	<i>+</i>
26	REAR END PANEL <i>Regis</i>	1	\$ 971.00	\$ 971.00	<i>+</i>
27	REAR END PANEL TOP GARNISH <i>Deland</i>	1	\$ 168.00	\$ 168.00	<i>-</i>

5602
5041.80

TOTAL PRICE \$ 12,360.00
 LESS 10% \$ 1,236.00
SUB TOTAL PRICE \$ 11,124.00

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>30</i>
3	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
4	REAR FENDER INNER COWLING (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
5	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
6	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00	<i>+</i>
7	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	<i>10</i>

40

TOTAL \$ 410.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	<i>600</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	<i>600</i>
3	TUFF COAT	\$ 250.00	<i>30</i>
4	WIRING CHECK	\$ 180.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR	\$ 250.00	<i>40</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>x</i>

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLD6237G**
 MODEL : **PEUGEOT 508**
 DATE OF ACCIDENT : 06.09.2024
 TIME OF ACCIDENT : 14:30 HOURS

8	TRANFER BOOT LID MECHANISM	\$ 80.00	X
9	CONDUCT WATER LEAKAGE TEST	\$ 150.00	X
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 380.00	X

1350

TOTAL \$4,850.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,534.00
 TOTAL LABOUR COST : \$ 4,850.00
 TOTAL REPAIR COST : \$ 16,384.00

Adrian L
 2/5 12/09/24
 05 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

Total: 6431.80
 L/S: 5150 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: