

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowok@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 12.09.2024

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SGH4004M
MODEL : NISSAN QASHQAI
DATE OF ACCIDENT : 11.09.2024
TIME OF ACCIDENT : 18:40 HOURS

Xiao Tany

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT NETT PRICE	TOTAL NETT PRICE
1	FRONT BUMPER <i>Repld</i>	1	\$ 683.00	\$ 683.00
2	FRONT BUMPER TOWING COVER <i>new</i>	1	\$ 34.60	\$ 34.60
3	FRONT BUMPER FOGLAMP COVER <i>new</i>	2	\$ 75.60	\$ 151.20
4	FRONT BUMPER FOGLAMP <i>Repld</i>	2	\$ 258.00	\$ 516.00
5	FRONT BUMPER SPONGE (UPPER) <i>Repld</i>	1	\$ 219.00	\$ 219.00
6	FRONT BUMPER SPONGE (LOWER) <i>new</i>	1	\$ 135.00	\$ 135.00
7	FRONT BUMPER REINFORCEMENT (UPPER) <i>Repld</i>	1	\$ 496.20	\$ 496.20
8	FRONT BUMPER REINFORCEMENT (LOWER) <i>new</i>	1	\$ 342.10	\$ 342.10
9	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 23.50	\$ 47.00
10	HEADLAMP (HID) <i>Repld</i>	2	\$ 612.20	\$ 1,224.40
11	HEADLAMP LOWER BRACKET <i>new</i>	2	\$ 17.00	\$ 34.00
12	FRONT GRILLE C/W CHROME & LOGO <i>lit</i>	1	\$ 575.20	\$ 575.20
13	FRONT FENDER <i>new</i>	2	\$ 685.40	\$ 685.40
14	FRONT FENDER INNER COWLING <i>new</i>	2	\$ 108.90	\$ 217.80
15	FRONT FENDER ARCED GARNISH <i>new RH</i>	2	\$ 541.40	\$ 1,082.80
16	BONNET <i>Repld</i>	1	\$ 1,061.30	\$ 1,061.30
17	BONNET LOCK <i>Repld</i>	1	\$ 67.60	\$ 67.60
18	BONNET INNER RUBBER <i>new</i>	1	\$ 72.40	\$ 72.40
19	BONNET INSULATOR <i>new</i>	1	\$ 296.70	\$ 296.70
20	BONNET STOPPER <i>new</i>	2	\$ 19.40	\$ 38.80
21	BONNET HINGE <i>new</i>	2	\$ 56.10	\$ 112.20

547.40

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SGH4004M
 MODEL : NISSAN QASHQAI
 DATE OF ACCIDENT : 11.09.2024
 TIME OF ACCIDENT : 18:40 HOURS

22	FRONT SUPPORT PANEL <i>Revised</i>	1	\$	628.70	\$	628.70	+
23	FRONT SUPPORT PANEL TOP COVER GARNISH <i>and changed</i>	1	\$	219.70	\$	219.70	+
24	RADIATOR <i>Dented</i>	1	\$	974.60	\$	974.60	✓
25	RADIATOR TOP SUPPORT GARNISH <i>and</i>	1	\$	187.50	\$	187.50	✓
26	RADIATOR LOWER SUPPORT GARNISH <i>new</i>	1	\$	175.30	\$	187.50	+
27	RADIATOR MOUNTING <i>new</i>	2	\$	19.60	\$	39.20	✓
28	AIR CON CONDENSER <i>Dented</i>	1	\$	879.90	\$	879.90	✓
29	AIR CON CONDENSER SIDE GARNISH <i>Dented</i>	2	\$	38.60	\$	77.20	✓
30	AIR CON SUCTION PIPE <i>3 MP</i>	1	\$	580.00	\$	580.00	+
31	AIR CON PRESSURE PIPE <i>new</i>	1	\$	730.00	\$	730.00	+
32	HORN <i>and</i>	2	\$	97.50	\$	195.00	✓
33	OIL COOLER <i>Dented and new</i>	1	\$	986.40	\$	986.40	✓
34	OIL COOLER PIPE <i>new</i>	1	\$	397.20	\$	397.20	+
35	TURBO COOLER <i>Dented</i>	1	\$	1,246.30	\$	1,246.30	✓
36	TURBO COOLER SIDE AIR GUARD <i>new</i>	1	\$	146.20	\$	1,246.30	+
37	REAR BUMPER <i>Dented</i>	1	\$	797.00	\$	797.00	✓
38	REAR BUMPER REFLECTOR <i>new</i>	2	\$	62.00	\$	124.00	+
39	REAR BUMPER TOWING COVER <i>new</i>	1	\$	19.00	\$	19.00	+
40	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$	39.00	\$	78.00	+
41	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$	692.00	\$	692.00	✓
42	REAR BUMPER REINFORCEMENT BRACKET <i>new</i>	2	\$	142.00	\$	284.00	+
43	REAR BUMPER LOWER SIDE BRACKET <i>new</i>	2	\$	26.00	\$	52.00	+
44	REAR BUMPER SPONGE <i>and</i>	1	\$	142.00	\$	142.00	✓
45	REAR FENDER INNER COWLING <i>new</i>	2	\$	202.00	\$	404.00	+
46	REAR FENDER ARCED GARNISH <i>new</i>	2	\$	540.00	\$	1,080.00	+
47	REAR FENDER INNER TRIM <i>new</i>	2	\$	496.10	\$	992.20	+
48	TAIL LAMP <i>new</i>	2	\$	347.00	\$	694.00	+
49	TAILGATE <i>new part</i>	1	\$	3,062.60	\$	3,062.60	+
50	TAILGATE LOGO <i>new</i>	1	\$	53.60	\$	53.60	✓
51	TAILGATE EMBLEM 'QASHQAI'	1	\$	95.00	\$	95.00	✓
52	TAILGATE LAMP <i>new</i>	2	\$	339.90	\$	679.80	+
53	TAILGATE NUMBER PLATE LAMP <i>new</i>	2	\$	24.40	\$	48.80	+
54	TAILGATE SWITCH BUTTOM	1	\$	73.00	\$	73.00	+
55	TAILGATE DAMPER	2	\$	98.00	\$	196.00	+
56	TAILGATE LOCK CATCH	1	\$	35.10	\$	35.10	+

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SGH4004M
 MODEL : NISSAN QASHQAI
 DATE OF ACCIDENT : 11.09.2024
 TIME OF ACCIDENT : 18:40 HOURS

57	TAILGATE INNER HOLDER	1	\$ 20.00	\$ 20.00	+
58	TAILGATE INNER LOCK	1	\$ 174.00	\$ 174.00	+
59	TAILGATE LOCK DETECTOR	1	\$ 168.70	\$ 168.70	+
60	TAILGATE INNER TRIM BOARD	1	\$ 496.50	\$ 496.50	+
61	TAILGATE WEATHER STRIP	1	\$ 167.00	\$ 167.00	+
62	TAILGATE WINDSCREEN C/W MOULDING	1	\$ 990.00	\$ 990.00	+
63	REAR END PANEL <i>Dented</i>	1	\$ 483.00	\$ 483.00	✓
64	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 69.00	\$ 69.00	✓
65	REAR TOOLS SPONGE COMPARTMENT <i>Scratched</i>	1	\$ 194.20	\$ 194.20	+
66	REAR TOOLS SPONGE COMPARTMENT BOLT <i>Scratched</i>	1	\$ 48.90	\$ 48.90	+
67	REAR TOOLS COMPARTMENT COVER BOARD (OUTER) <i>Scratched</i>	1	\$ 528.00	\$ 528.00	✓
68	REAR TOOLS COMPARTMENT COVER BOARD (INNER) <i>Scratched</i>	1	\$ 572.00	\$ 572.00	+
69	REVERES CAMERA <i>Scratched</i>	1	\$ 929.60	\$ 929.60	+

1304950 TOTAL PRICE \$ 31,111.20
 1174455 LESS 10% \$ 3,111.12
 SUB TOTAL PRICE \$ 28,000.08

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BUMPER CLIP (SET) <i>Scratched</i>	1	\$ 80.00	\$ 80.00	30
2	FRONT FENDER INNER COWLING (CLIP) (SET) <i>Scratched</i>	1	\$ 60.00	\$ 60.00	+
3	BONNET INSULATOR CLIP <i>Scratched</i>	1	\$ 80.00	\$ 80.00	+
4	COOLANT <i>Scratched</i>	1	\$ 120.00	\$ 120.00	50
5	REAR NUMBER PLATE <i>Scratched</i>	1	\$ 80.00	\$ 80.00	+
6	REAR BUMPER CLIP (SET) <i>Scratched</i>	1	\$ 80.00	\$ 80.00	30
7	TAILGATE WINDSCREEN SEALANT <i>Scratched</i>	1	\$ 80.00	\$ 80.00	+
8	TAILGATE WINDSCREEN INNER SEAL <i>Scratched</i>	1	\$ 60.00	\$ 60.00	+
9	TAILGATE WINDSCREEN SOLAR FILM <i>Scratched</i>	1	\$ 550.00	\$ 550.00	+
10	REVERSE SENSOR (4PCS) <i>Damaged</i>	1	\$ 360.00	\$ 360.00	300

430

TOTAL \$ 1,550.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,600.00	600

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SGH4004M
 MODEL : NISSAN QASHQAI
 DATE OF ACCIDENT : 11.09.2024
 TIME OF ACCIDENT : 18:40 HOURS

2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	400
3	WIRING CHECK	\$ 120.00	30
4	REFOCUS HEADLAMP BEAM	\$ 80.00	x
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	60
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60
7	REMOVE AND REFIX AIR COOLER AND OIL COOLER	\$ 180.00	60
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

1210

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	600
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	600
3	TUFF COAT	\$ 250.00	60
4	TRANSFER TAILGATE MECHANISM	\$ 80.00	x
5	REMOVE AND REFIX TAIL GATE WINDSCREEN	\$ 120.00	x
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX REAR REVERSE CAMERA	\$ 80.00	x
8	REMOVE AND REFIX VIDEO RECORDER	\$ 80.00	x

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SGH4004M
MODEL : NISSAN QASHQAI
DATE OF ACCIDENT : 11.09.2024
TIME OF ACCIDENT : 18:40 HOURS

9	CONDUCT WATER LEAKAGE TEST	\$ 180.00	X
---	----------------------------	-----------	---

1310

TOTAL \$ 8,230.00

TOTAL PARTS COST : \$ 29,550.08
TOTAL LABOUR COST : \$ 8,230.00
TOTAL REPAIR COST : \$ 37,780.08

Adrian
r/s 12/09/24
10 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

Nett Value : 9K.

total: 14694.55

L/s: 9K (Nett Value)
✓

KK Auto Consultants hereby
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: