



# DPS

**Diplomat Parts Pte. Ltd.**Company Reg No. 196400304H  
GST Reg No. MR-8500111-X

## ESTIMATE

Invoice Name &amp; Address

Owner Name &amp; Vehicle Info

Cycle &amp; Carriage Leasing Pte Ltd

239 ALEXANDRA ROAD

Singapore 159930  
159930

Contact No Mobile: 91185739

Reg No/Reg Date

GBM4389K / 15/09/2023

Date In/Mileage

10/09/2024/ 30899

Chassis No

\*W1V44760324208454

Engine No

Make/Model

EVITO 112 LONG AT

| Account No                      | Terms | Date/Time Printed | CSE | Operator            | WIP No                  |
|---------------------------------|-------|-------------------|-----|---------------------|-------------------------|
| CSM00061                        | Cash  | 10/09/2024/ 11:26 | TLL | 1210/ Lim Teng Keat | 33451                   |
| Description of Goods / Services |       |                   |     | Qty                 | Unit Price Disc% Amount |

Z TEXT

TP CLAIM MS FIRST CAPITAL

DOA 03/09/2024

SUR LKK

00 REPAIR DAYS

E PNT88000

TO REPLACE FRT BUMPER, FRT LHS FENDER, HEADLAMP  
AND REPAIR ACCIDENT AFFECTED AREA

E PNT98000

PAINT WORK ON FRT BUMPER, FRT LHS FENDER, FRT LHS DOOR

M SUNDRY

ANTI-RUST PROOFING

M SUNDRY

APPLY BODY SEALANT ON AFFECTED AREA

A WHEELALIGNMENT120L

To Conduct Computerize Full Wheel Alignment

A 54900099

TO CHECK WIRING CHASSIS ELECTRICAL AND EV SYSTEM

A 10028901

TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM

M SUNDRY

SUNDRIES

M SUNDRY

TRIM, BUMPER

FRT BUMPER

M SUNDRY

REINFORCEMENT, BUMPER

FRT BUMPER LHS FRAME

M SUNDRY

COVER

FRT BUMPER LHS GRILLE

M SUNDRY

MOUNTING RAIL

~~1000~~ 1350.00~~900~~ 1600.00~~60~~ 160.00~~60~~ 160.00~~17 X 8~~ 250.00~~100~~ 200.00~~280~~ 380.00~~20~~ 80.00

2440.43

158.98

58.81

79.38

# Estimate

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

**DPS Auto Services**



# DPS

Diplomat Parts Pte. Ltd.

Company Reg No. 196400304H  
GST Reg No. MR-8500111-X

## ESTIMATE

### Invoice Name & Address

### Owner Name & Vehicle Info

Cycle & Carriage Leasing Pte Ltd

239 ALEXANDRA ROAD

Singapore 159930  
159930

Contact No Mobile: 91185739

Reg No/Reg Date

GBM4389K / 15/09/2023

Date In/Mileage

10/09/2024/ 30899

Chassis No

\*W1V44760324208454

Engine No

Make/Model

EVITO 112 LONG AT

| Account No | Terms | Date/Time Printed | CSE | Operator            | WIP No |
|------------|-------|-------------------|-----|---------------------|--------|
| CSM00061   | Cash  | 10/09/2024/ 11:26 | TLL | 1210/ Lim Teng Keat | 33451  |

| Description of Goods / Services                       | Qty | Unit Price | Disc% | Amount          |
|-------------------------------------------------------|-----|------------|-------|-----------------|
| FRT BUMPER LHS FENDER STAY <i>crn /</i>               |     |            |       | 32.00           |
| M SUNDRY BRACING                                      |     |            |       |                 |
| FRT BUMPER LHS FENDER STAY BRACING <i>? x s/c</i>     |     |            |       | 31.10           |
| M SUNDRY ELECTRICAL WIRING HARNESS <i>? x s/c</i>     |     |            |       |                 |
| CHARGE SOCKET TO BUMPER                               |     |            |       |                 |
| M SUNDRY CENTRAL LOCKING MOTOR <i>? x s/c</i>         |     |            |       | 94.96           |
| CAHRDING FLAP LOCKING MOTOR                           |     |            |       |                 |
| M SUNDRY BUTTON SWITCH <i>? x s/c</i>                 |     |            |       | 106.71          |
| CHARGING FLAP OPENING AND CLOSE SWITCH <i>? x s/c</i> |     |            |       |                 |
| M SUNDRY COUPLING, MECHANICAL <i>? x s/c</i>          |     |            |       | 46.00           |
| PARKTRONIC SENSOR SEAL                                |     |            |       |                 |
| M SUNDRY CLUTCH HOUSING <i>? x s/c</i>                |     |            |       | 15.20           |
| PARKTRONIC SENSOR HOUSING                             |     |            |       |                 |
| M SUNDRY ELECTRICAL WIRING HARNESS <i>? x s/c</i>     |     |            |       | 413.66          |
| FRT BUMPER WIRE HARNESS                               |     |            |       |                 |
| M SUNDRY LAMP UNIT <i>bro /</i>                       |     |            |       | 795.43          |
| FRT LHS HEADLAMP                                      |     |            |       |                 |
| M SUNDRY FENDER, FRONT <i>bro /</i>                   |     |            |       | (889.19) 899.19 |
| M SUNDRY HEXALOBULAR BOLT * 5 PCS <i>bro /</i>        |     |            |       | 36.00           |
| FENDER BOLT                                           |     |            |       |                 |
| M SUNDRY HOLDER                                       |     |            |       | 9.68            |
| FRT LHS FENDER COVER HOLDER <i>? x s/c</i>            |     |            |       |                 |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

DPS Auto Services





# DPS

## Diplomat Parts Pte. Ltd.

Company Reg No. 196400304H  
GST Reg No. MR-8500111-X

### ESTIMATE

Invoice Name & Address

Owner Name & Vehicle Info

Cycle & Carriage Leasing Pte Ltd

239 ALEXANDRA ROAD

Singapore 159930  
159930

Contact No Mobile: 91185739

Reg No/Reg Date GBM4389K / 15/09/2023

Date In/Mileage 10/09/2024/ 30899

Chassis No \*W1V44760324208454

Engine No

Make/Model EVITO 112 LONG AT

| Account No                      | Terms  | Date/Time Printed                     | CSE | Operator            | WIP No |            |       |         |
|---------------------------------|--------|---------------------------------------|-----|---------------------|--------|------------|-------|---------|
| CSM00061                        | Cash   | 10/09/2024/ 11:26                     | TLL | 1210/ Lim Teng Keat | 33451  |            |       |         |
| Description of Goods / Services |        |                                       |     |                     | Qty    | Unit Price | Disc% | Amount  |
| M                               | SUNDRY | INTERMEDIATE LAYER                    |     |                     |        |            |       | 16.00   |
|                                 |        | FRT LHS FENDER FOAM LAYER             |     |                     |        |            |       |         |
| M                               | SUNDRY | TRIM, WHEEL HOUSING                   |     |                     |        |            |       | 178.68  |
|                                 |        | FRT LHS FENDER WHEEL HOUSE COVER      |     |                     |        |            |       |         |
| M                               | SUNDRY | EXPANSION RIVET * 5 PCS               |     |                     |        |            |       | 80.00   |
|                                 |        | FRT LHS FENDER CLIP                   |     |                     |        |            |       |         |
| M                               | SUNDRY | PLASTIC NUT                           |     |                     |        |            |       | 96.00   |
|                                 |        | FRT LHS FENDER WHEEL HOUSE COVER CLIP |     |                     |        |            |       |         |
| M                               | SUNDRY | CROSSMEMBER                           |     |                     |        |            |       | 1120.02 |
|                                 |        | FRT REINFORCEMENT                     |     |                     |        |            |       |         |
| M                               | SUNDRY | CARRIER                               |     |                     |        |            |       | 472.74  |
|                                 |        | HEADLAMP PANEL                        |     |                     |        |            |       |         |
| M                               | SUNDRY | HOLDER                                |     |                     |        |            |       | 50.00   |
|                                 |        | HOLDER FOR RADAR SENSOR BRACKET       |     |                     |        |            |       |         |
| M                               | SUNDRY | HOLDER                                |     |                     |        |            |       | 81.46   |
|                                 |        | HOLDER FOR LHS MODULE                 |     |                     |        |            |       |         |
| M                               | SUNDRY | BUMPER HOLDER                         |     |                     |        |            |       | 63.58   |
|                                 |        | FRT BUMPER SUPPORT HOLDER             |     |                     |        |            |       |         |
| M                               | SUNDRY | LINK BLOCK                            |     |                     |        |            |       | 21.46   |
|                                 |        | BRACKET TO LHS MODULE                 |     |                     |        |            |       |         |
| M                               | SUNDRY | LINK BLOCK                            |     |                     |        |            |       | 30.00   |
|                                 |        |                                       |     |                     |        |            |       |         |
| M                               | SUNDRY |                                       |     |                     |        |            |       | 77.91   |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

DPS Auto Services

ESTIMATE

Invoice Name & Address

Owner Name & Vehicle Info

Cycle & Carriage Leasing Pte Ltd

239 ALEXANDRA ROAD

Singapore 159930  
159930

Contact No Mobile: 91185739

Reg No/Reg Date GBM4389K / 15/09/2023

Date In/Mileage 10/09/2024/ 30899

Chassis No \*W1V44760324208454

Engine No

Make/Model EVITO 112 LONG AT

|                                 |       |                   |     |                     |            |       |        |
|---------------------------------|-------|-------------------|-----|---------------------|------------|-------|--------|
| Account No                      | Terms | Date/Time Printed | CSE | Operator            | WIP No     |       |        |
| CSM00061                        | Cash  | 10/09/2024/ 11:26 | TLL | 1210/ Lim Teng Keat | 33451      |       |        |
| Description of Goods / Services |       |                   |     | Qty                 | Unit Price | Disc% | Amount |

SOCKET COVER

CHARGE COVER

M SUNDRY

CENTRAL LOCKING MOTOR

CHARGE SOCKET LOCK

300.85

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: KASIM - 4p 9w1w68

SURVEYOR SIGNATURE: [Signature]

DATE: 09/09/24

REMARKS: 4 days + 1 = 5 days  
Per 64 print

Confirm & accepted by

|           |          |           |
|-----------|----------|-----------|
|           | Nett     | 11,988.23 |
| 9% GST on | 11988.23 | 1078.94   |

Total Payable 13,067.17

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

**DPS Auto Services**

209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792





**Diplomat Parts Pte. Ltd.**

Company Reg No. 196400304H  
GST Reg No. MR-8500111-X

## ESTIMATE

### Invoice Name & Address

Cycle & Carriage Leasing Pte Ltd

239 ALEXANDRA ROAD

Singapore 159930  
159930

Contact No Mobile: 91185739

### Owner Name & Vehicle Info

Reg No/Reg Date GBM4389K / 15/09/2023

Date In/Mileage 10/09/2024/ 30899

Chassis No \*W1V44760324208454

Engine No

Make/Model EVITO 112 LONG AT

| Account No                                           | Terms                 | Date/Time Printed    | CSE | Operator            | WIP No     |       |        |
|------------------------------------------------------|-----------------------|----------------------|-----|---------------------|------------|-------|--------|
| CSM00061                                             | Cash                  | 11/01/2025/ 10:20    | TLL | 1210/ Lim Teng Keat | 33451      |       |        |
| Description of Goods / Services                      |                       |                      |     | Qty                 | Unit Price | Disc% | Amount |
| A WHEELALIGNMENT120L                                 |                       |                      |     |                     |            |       | 250.00 |
| To Conduct Computerize Full Wheel Alignment          |                       |                      |     |                     |            |       |        |
| S SPECIALISTJOB                                      |                       |                      |     |                     |            |       | 380.00 |
| TO SUPPLY 4 POINTS PARKING SENSOR FOR FRONT MB EVITO |                       |                      |     |                     |            |       |        |
| X                                                    | WMA4478810000         | <del>cm</del> REPEAT |     | 1.00                | 32.00      | 00.00 | 32.00  |
| BRACING                                              |                       |                      |     |                     |            |       |        |
| X                                                    | MA447 880 37 02/ 9051 | <del>cm</del> REPEAT |     | 1.00                | 158.98     | 00.00 | 158.98 |
| REINFORCEMENT, BUMPER                                |                       |                      |     |                     |            |       |        |
| X                                                    | MA447 880 11 03       | <del>cm</del>        |     | 1.00                | 472.74     | 00.00 | 472.74 |
| CARRIER                                              |                       |                      |     |                     |            |       |        |
| X                                                    | MA447 885 89 00       | <del>cm</del>        |     | 1.00                | 21.46      | 00.00 | 21.46  |
| LINK BLOCK                                           |                       |                      |     |                     |            |       |        |
| X                                                    | MA447 885 90 00       | <del>cm</del>        |     | 1.00                | 63.58      | 00.00 | 63.58  |
| BUMPER HOLDER                                        |                       |                      |     |                     |            |       |        |
| X                                                    | MA447 817 70 01       | <del>cm</del>        |     | 1.00                | 38.92      | 00.00 | 38.92  |
| BADGE                                                |                       |                      |     |                     |            |       |        |
| X                                                    | MA447 885 89 00       | <del>cm</del>        |     | 1.00                | 21.46      | 00.00 | 21.46  |
| LINK BLOCK                                           |                       |                      |     |                     |            |       |        |
| X                                                    | MA447 400 10 00/ 9705 | <del>cm</del>        |     | 1.00                | 103.48     | 00.00 | 103.48 |
| HUB CAP                                              |                       |                      |     |                     |            |       |        |
| X                                                    | MA447 885 92 00/ 9051 | <del>cm</del>        |     | 1.00                | 58.81      | 00.00 | 58.81  |
| COVER                                                |                       |                      |     |                     |            |       |        |

Estimate

Suppl

Suppl

Confirm & accepted by

9% GST on      **Nett**      1,601.43  
1601.43      144.13

Authorized signatory and company stamp

**Total Payable**      1,745.56

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

**DPS Auto Services**

209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792