



Diplomat Parts Pte. Ltd.

Company Reg No. 196400304H
GST Reg No. MR-8500111-X

ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info	
Cycle & Carriage Leasing Pte Ltd		Reg No/Reg Date	GBM4389K / 15/09/2023
239 ALEXANDRA ROAD		Date In/Mileage	10/09/2024/ 30899
Singapore 159930		Chassis No	*W1V44760324208454
159930		Engine No	
Contact No	Mobile: 91185739	Make/Model	EVITO 112 LONG AT

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00061	Cash	11/01/2025/ 10:20	TLL	1210/ Lim Teng Keat	33451			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z	TEXT							
	TP CLAIM MS FIRST CAPITAL							
	DOA 03/09/2024							
	SUR LKK							
	00 REPAIR DAYS							
E	PNT88000							1000.00
	TO REPLACE FRT BUMPER, FRT LHS FENDER, HEADLAMP							
	AND REPAIR ACCIDENT AFFECTED AREA							
E	PNT98000							900.00
	PAINT WORK ON FRT BUMPER, FRT LHS FENDER, FRT LHS DOOR							
M	SUNDRY							60.00
	ANTI-RUST PROOFING							
M	SUNDRY							60.00
	APPLY BODY SEALANT ON AFFECTED AREA							
A	WHEELALIGNMENT120L							250.00
	To Conduct Computerize Full Wheel Alignment							
A	54900099							100.00
	TO CHECK WIRING CHASSIS ELECTRICAL AND EV SYSTEM							
A	10028901							280.00
	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
M	SUNDRY							20.00
	SUNDRIES							
S	SPECIALISTJOB							380.00
	TO SUPPLY 4 POINTS PARKING SENSOR FOR FRONT MB EVITO							
X	WMA4478807103/9B51				1.00	2440.43	00.00	2440.43
	TRIM BUMPER							
X	MA447 880 06 12				1.00	79.38	00.00	79.38
	MOUNTING RAIL							
X	WMA4479067900				1.00	795.43	00.00	795.43
	LAMP UNIT							
X	WMA4478804101				1.00	889.19	00.00	889.19
	FENDER FRONT							

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

DPS Auto Services

209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792



Diplomat Parts Pte. Ltd.

Company Reg No. 196400304H
GST Reg No. MR-8500111-X

ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info	
Cycle & Carriage Leasing Pte Ltd		Reg No/Reg Date	GBM4389K / 15/09/2023
239 ALEXANDRA ROAD		Date In/Mileage	10/09/2024/ 30899
Singapore 159930		Chassis No	*W1V44760324208454
159930		Engine No	
Contact No	Mobile: 91185739	Make/Model	EVITO 112 LONG AT

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00061	Cash	11/01/2025/ 10:20	TLL	1210/ Lim Teng Keat	33451			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
X	WMA4478890095				1.00	16.00	00.00	16.00
	INTERMEDIATE LAYER							
X	WMA4476840177				1.00	178.68	00.00	178.68
	TRIM WHEEL HOUSING							
X	WMA1249900492				5.00	16.00	00.00	80.00
	EXPANSION RIVET							
X	WMA2019900050				6.00	16.00	00.00	96.00
	PLASTIC NUT							
X	WMA4478810000				1.00	32.00	00.00	32.00
	BRACING							
X	MA447 880 37 02/ 9051				1.00	158.98	00.00	158.98
	REINFORCEMENT, BUMPER							
X	MA447 880 11 03				1.00	472.74	00.00	472.74
	CARRIER							
X	MA447 885 89 00				1.00	21.46	00.00	21.46
	LINK BLOCK							
X	MA447 885 90 00				1.00	63.58	00.00	63.58
	BUMPER HOLDER							
X	MA447 817 70 01				1.00	38.92	00.00	38.92
	BADGE							
X	MA447 885 89 00				1.00	21.46	00.00	21.46
	LINK BLOCK							
X	MA447 400 10 00/ 9705				1.00	103.48	00.00	103.48
	HUB CAP							
X	MA447 885 92 00/ 9051				1.00	58.81	00.00	58.81
	COVER							

Confirm & accepted by

Authorized signatory and company stamp

Nett 8,596.54
9% GST on 8596.54 773.69

Total Payable 9,370.23

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

DPS Auto Services

209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792