



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24090307/Avp3m4
16 RAFFLES QUAY	Date:	25/11/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 458M	Veh. Inspected	SNL 8109P
Policy No.	-	Coverage	0
Claim No.	D24008149MFCT	Excess	\$0.00
Assign From	JOANNE	Assign Date	17/09/2024

2. Vehicle Details

Make & Model	SUBARU FORESTER	C.C	1995
Engine No.	FB20YN64281	Year of Reg.	29/07/2022
Chassis No.	JF1SK7KL5MG060084	Colour	RED
Odometer	33825 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/60R17	BRIDGESTONE	6
L/H Front Tyre	225/60R17	BRIDGESTONE	6
R/H Rear Tyre	225/60R17	BRIDGESTONE	6
L/H Rear Tyre	225/60R17	BRIDGESTONE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/09/2024	Inspection Date	17/09/2024
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days