

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GHAZALI BIN ABDULLAH @RAJAMOHAN S/O
 RAJAGOPAL
 BLK 236 CHOA CHU KANG CENTRAL #04-43
 SINGAPORE 680236

Contact : 92261661

TP 1st Cap.
 Veron.

TAX INVOICE

Repair Code : CLM18380

Date in : 16/09/2024

Vehicle Num. : SNL8109P

Model : SUBARU FORESTER 2.0I-L EYESIGHT AWD CVT

Chassis/Eng# : JF1SK7KL5MG060084/FB20YN64281

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>torn</i>	1	917.40	✓ 917.40
REAR BUMPER LOWER DIFFUSER <i>cut</i>	1	333.40	✓ 333.40
REAR BUMPER REVERSE SENSOR <i>new</i>	2	294.20	+ 588.40
REAR BUMPER REVERSE SENSOR 'O' RING <i>new</i>	4	25.00	+ 100.00
REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	4	65.60	+ 262.40
REAR BUMPER RH REFLECTOR <i>new</i>	1	249.20	+ 249.20
REAR BUMPER RH SIDE RETAINER <i>new</i>	1	25.50	+ 25.50
REAR BUMPER TOW HOOK COVER <i>new</i>	1	21.60	+ 21.60
REAR RH KNUCKLE ARM <i>new</i>	1	342.60	+ 342.60
REAR RH KNUCKLE ARM BEARING <i>new</i>	1	266.60	+ 266.60
REAR RH SPORT RIM <i>cut</i>	1	898.60	+ 898.60
Subtotal before discount			4,005.70
Percentage discount 10%			400.57
Sub-total 1			3,605.13
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	30 50.00
REAR RH TYRE <i>new</i>	1	380.00	+ 380.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HAZALI BIN ABDULLAH @RAJAMOHAN S/O
RAJAGOPAL
BLK 236 CHOA CHU KANG CENTRAL #04-43
SINGAPORE 680236

Contact : 92261661

TAX INVOICE

Repair Code : CLM18380

Date in : 16/09/2024

Vehicle Num. : SNL8109P

Model : SUBARU FORESTER 2.0I-L EYESIGHT AWD CVT

Chassis/Eng# : JF1SK7KL5MG060084/FB20YN64281

	Subtotal before discount	430.00
Percentage discount 0%		0.00
	Sub-total 2	430.00
	Parts-total	4,035.13

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	80.00
To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	120.00
To road test driving, check and resetting wheel alignments system.	100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	500.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	500.00
To apply anti-rust chemical on repaired and replaced panel.	60.00
Labour Total	1,360.00
Parts & Labour Total	5,395.13

*** This is a computer-generated document which requires no signature.***

page 2
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Admin L
15/9 17/09/24
032ys
Total 204064.
H/S: 1.6K ✓