

TP 1st Cap.
Hui Rong

18 Sep 2024

KMHC851CVNU293429.

SNG 1091 C HYUNDAI IONIQ

No	Qty	Parts Description	Estimated Parts Price
1	1	Front headlamp -LH <i>lit</i>	\$ 3,034.90 <i>2110</i>
2	1	Front headlamp lower bracket <i>could</i>	\$ 127.60 ✓
3	1	Front bumper <i>De-lid</i>	\$ 525.00 ✓
4	1	Front bumper side lamp <i>could</i>	\$ 400.30 <i>320</i>
5	1	Front bumper side lamp grille <i>could</i>	\$ 150.20 -
6	1	Front bumper reinforcement <i>new</i>	\$ 696.00 +
7	1	Front bumper side retainer <i>could</i>	\$ 60.20 ✓
8	1	Front fender -LH <i>Dented</i>	\$ 1,521.60 <i>480</i>
9	1	Front fender inner shield <i>new</i>	\$ 220.80 ✓
10	1	Front wheel rim <i>new</i>	\$ 1,550.00 +
11	1	Front wheel hub <i>new</i>	\$ 189.50 +
12	1	Front wheel bearing <i>new</i>	\$ 155.80 ✓
13	1	Front shock absorber <i>new</i>	\$ 424.50 +
14	1	Front knuckle arm <i>new</i>	\$ 455.80 +
15	1	Front lower arm <i>new</i>	\$ 435.00 +
			\$ 9,947.20
			\$ 994.72
			\$ 8,952.48

less 10%

20%

4099.40

3279.52

No	Qty	Parts Description	Estimated Parts Price
		<u>Special Nett Items</u>	
1	1	Front bumper clip (1 set) <i>new</i>	\$ 80.00 <i>30</i>
2	1	Front fender inner shield clip (1 set) <i>new</i>	\$ 60.00 <i>30</i>
3	1	Front tyre <i>new</i>	\$ 400.00 +
4	1	Front sport rim <i>Cones</i>	\$ 500.00 <i>new</i>
			\$ 1,040.00

Total parts : \$ 9,992.48

No	Description	Labour Charges
1	To check wiring , lighting and resetting headlamps focusing.	\$ 80.00 30
2	To remove and refit front undercarriage.	\$ 300.00 60
3	To conduct wheel alignment.	\$ 180.00 80
4	To apply undercoating on repaired and replaced panel.	\$ 180.00 +
5	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	1070 \$ 1,600.00 500
6	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,500.00 400

Total labour : \$ 3,840.00

Total parts : \$ 9,992.48

Total labour : \$ 3,840.00

Total repair cost : \$ 13,832.48

Adrian G
H/S 17/09/24
OSang
Total: 460952
H/S: 3.6K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: