

ASSIGNMENT

Front: _____ Date: _____

Estin: _____

OD / TP RES / OD RES / EVA / INV / MV

To in Vehicle No: _____

at W/O m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vek: _____

(Policy Condition)

N/S	O/S

Remark: Tlevh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNG1091C Yr Regn: 2022, July

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Ioniq C.D. 1580

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 15480/1 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHC851CVNU293429

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15
R: 185/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

A Plus

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 17/09/24

Survey held at

A-Tec

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 1st Rep.

COE Expiry

Estimate given during: Yes (✓)
1st Survey: No ()

MV: 118K

PV: 68.7K

Nett: 49.3K

244G

Date/Time, File Pass to?

☐: Preli. Report

Days Of Repair: _____

1) _____

☐: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: _____

2) _____

Transportation: _____

Add Fee: ☐: Site Insp (\$ _____)

Photos

☐: Interview (\$ _____)

Others

☐: Tech. Insp (\$ _____)

Report Format: _____

Report Form & P.P. (in _____)

A-Tec Automotive Pte Ltd
8 Kaki Bukit Ave 4
#04-20 Premier
Singapore 415875

18 Sep 2024

SNG 1091 C HYUNDAI IONIQ

No	Qty	Parts Description	Estimated Parts Price
1	1	Front headlamp -LH <i>ut</i>	\$ 3,034.90 ✓
2	1	Front headlamp lower bracket <i>could</i>	\$ 127.60 ✓
3	1	Front bumper <i>De led</i>	\$ 525.00 ✓
4	1	Front bumper side lamp <i>could</i>	\$ 400.30 ✓
5	1	Front bumper side lamp grille <i>could</i>	\$ 150.20 -
6	1	Front bumper reinforcement <i>new</i>	\$ 696.00 +
7	1	Front bumper side retainer <i>could</i>	\$ 60.20 ✓
8	1	Front fender -LH <i>De led</i>	\$ 1,521.60 ✓
9	1	Front fender inner shield <i>new ton</i>	\$ 220.80 ✓
10	1	Front wheel rim <i>set new</i>	\$ 1,550.00 +
11	1	Front wheel hub <i>new</i>	\$ 189.50 +
12	1	Front wheel bearing <i>new</i>	\$ 155.80 ✓
13	1	Front shock absorber <i>new</i>	\$ 424.50 +
14	1	Front knuckle arm <i>new</i>	\$ 455.80 +
15	1	Front lower arm <i>new</i>	\$ 435.00 +
			\$ 9,947.20
			less 10%
			\$ 994.72
			<u>\$ 8,952.48</u>

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	1	Front bumper clip (1 set) <i>new</i>	\$ 80.00 30
2	1	Front fender inner shield clip (1 set) <i>new</i>	\$ 60.00 30
3	1	Front tyre <i>new</i>	\$ 400.00 +
4	1	Front sport rim <i>cover ut</i>	\$ 500.00 200
			<u>\$ 1,040.00</u>

Total parts : \$ 9,992.48

No	Description	Labour Charges	
1	To check wiring , lighting and resetting headlamps focusing.	\$ 80.00	30
2	To remove and refit front undercarriage.	\$ 300.00	60
3	To conduct wheel alignment.	\$ 180.00	80
4	To apply undercoating on repaired and replaced panel.	\$ 180.00	+
5	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,600.00	500
6	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,500.00	400

Total labour : \$ 3,840.00

Total parts : \$ 9,992.48

Total labour : \$ 3,840.00

Total repair cost : \$ 13,832.48

Adrian G
L/S 17/09/24
OSays

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: