

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	SOMPO INSURANCE SINGAPORE PL		Ref:	CS/SMO24090309/Kqp3m4	
	50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWER SINGAPORE 048623		Date:	10/12/2024	
	SINGAL ONE LAND TOWER SINGAFORE 040023		Code:	SMO	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SNA 8073R	Veh. Inspected	SLZ 1286G	
	Policy No.	-	Coverage	0	
	Claim No.	CMTD2402970/JYC	Excess	\$0.00	
	Assign From	JIA YI	Assign Date	17/09/2024	
2.	2. Vehicle Details				
	Make & Model	NISSAN PULSAR (A)	C.C	1197	
	Engine No.	HRA2395712A	Year of Reg.	07/07/2017	
	Chassis No.	VSKDDAC13U0098582	Colour	RED	
	Odometer	103117 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	3. Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	205/50R17	BRIDGESTONE	9	
	L/H Front Tyre	205/50R17	BRIDGESTONE	9	
	R/H Rear Tyre	205/50R17	BRIDGESTONE	9	
	L/H Rear Tyre	205/50R17	BRIDGESTONE	9	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	14/09/2024	Inspection Date	18/09/2024	
	Survey held at	VENTURES AUTO PTE LTD - 1 SIN M	IING IND. SECTOR	C #01-111/113 SINGAPORE 575636	
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
50. Estimate Days of Repair					

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days